


**COLORADO OIL & GAS CONSERVATION COMMISSION  
FIELD INSPECTION REPORT**



<input checked="" type="checkbox"/> NOTICE OF UNSATISFACTORY INSPECTION	1120 Lincoln Street, Suite 801 Denver, CO 80203 (303)894-2100
<input type="checkbox"/> NOTICE OF SATISFACTORY INSPECTION	
API No. 05- <i>075 - 8507-1</i>	LEASE NAME: <i>Emerald Unit 4-35</i>
LOCATION: <i>NE3W 35-9N-54</i>	OPERATOR: <i>Walsh Prod</i>
DATE: <i>11-13-97</i>	INSPECTOR: <i>Ed Bentley</i>
Insp. Type: <i>SR</i>	Insp. Status: <i>PA</i>
PA: Y <input checked="" type="radio"/> N	Pass/Fail: P <input checked="" type="radio"/> F
	Viol.: Y <input checked="" type="radio"/> N
	NOV: Y <input checked="" type="radio"/> N

INSPECTION ITEM	COMMENTS	INPUT
<b>Well ID Signs</b> (Rule 210, 604.c(4))		
<b>Pits (Reserve/Production)</b> (Rule 902, 903, 904, 905)		
<b>Fences</b> (Rule 603.b.7, 604.C.(3), 1002.A)		
<b>Tank Battery Equipment</b> (Rule 603.b.3, 604)		
<b>Fire Walls/Berms/Dikes</b> (Rule 603.b.12, 604)		
<b>General Housekeeping</b> (Rule 603)		
<b>Spills (Oil/Water)</b> (Rule 907)		
<b>Bradenhead</b> (Rule 207.b)		
<b>Drilling Well/Workover</b> (Rule 317)		
<b>Surface Rehabilitation</b> (Rule 1002, 1003, 1004, 1103)	<i>grass / may need reseeding.</i>	
<b>Miscellaneous</b>	<i>Reported leaking flowline valve to Frank Walsh</i>	



**CORRECTIVE ACTION REQUIRED:** *Remove flow line riser @ site.  
Rip and reseed access road to above site.*

Date Corrective Action Required By: \_\_\_\_\_ Date Remedied: \_\_\_\_\_

This report is a Notice of Inspection. The Commission requires that you correct any deficiencies shown on this report in a timely manner. Failure to comply may result in enforcement action by the Commission.