

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

401760543

Date Received:

09/12/2018

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10672

Name of Operator: TIMBER CREEK OPERATING LLC

Address: 6295 GREENWOOD PLAZA BLVD #100

City: GREENWOOD VILLAGE State: CO Zip: 8111-4978

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

Santistevan, Vince

719-845-2102/719-680-9705

vincesantistevan@tcenergy.us

Amato, Joseph

719-845-2110/719-859-2263

josephamato@tcenergy.us

COGCC INSPECTION SUMMARY:

FIR Document Number: 687903037

Inspection Date: 08/22/2018

FIR Submit Date: 08/23/2018

FIR Status: _____

Inspected Operator Information:

Company Name: TIMBER CREEK OPERATING LLC

Company Number: 10672

Address: 1001 17TH STREET #1000

City: DENVER State: CO Zip: 80202

LOCATION - Location ID: 308127

Location Name: APACHE CANYON-634S68W Number: 26SENE County: LAS ANIMAS

Qtrqtr: SENE Sec: 26 Twp: 34S Range: 68W Meridian: 6

Latitude: 37.055290 Longitude: -104.958920

FACILITY - API Number: 05-071- -00 Facility ID: 262542

Facility Name: APACHE CANYON Number: 26-8V

Qtrqtr: SENE Sec: 26 Twp: 34S Range: 68W Meridian: 6

Latitude: 37.055290 Longitude: -104.958920

CORRECTIVE ACTIONS:

1 ☒ CA# 118139

Corrective Action: Equipment not in use needs to be taken off site.

Date: 09/23/2018

Response: CA COMPLETED

Date of Completion: 09/11/2018

Operator Comment: All unused equipment was removed from location. See attached photo log for details.

COGCC Decision: Approved pending re-inspection

Need to put lease sign back up.

Date of Completion: 09/11/2018

The lease sign was reattached to the separator door. See attached photo log for details.

Comment:	All of the unused equipment has been removed from the location. The lease sign was reattached to the separator door. Both corrective actions have been addressed.
----------	---

Signed:

Date: 9/12/2018 10:53:17 AM

<u>Document Number</u>	<u>Description</u>
401760543	FIR RESOLUTION SUBMITTED
401760561	Unused equipment removed and lease sign reattached to door

Page 2 of 2