

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
401810445

Date Received:
10/25/2018

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10672
Name of Operator: TIMBER CREEK OPERATING LLC
Address: 6295 GREENWOOD PLAZA BLVD #100
City: GREENWOOD VILLAGE State: CO Zip: 8111-4978

Contact Name and Telephone:
Name: _____
Phone: () _____ Fax: () _____
Email: _____

Additional Operator Contact:

Contact Name	Phone	Email
<u>Santistevan, Vince</u>	<u>719-845-2102/719-680-9705</u>	<u>vincasantistevan@tcenergy.us</u>
<u>Amato, Joseph</u>	<u>719-845-2110/719-859-2263</u>	<u>josephamato@tcenergy.us</u>

COGCC INSPECTION SUMMARY:

FIR Document Number: 687903213
Inspection Date: 09/24/2018 FIR Submit Date: 09/27/2018 FIR Status: _____

Inspected Operator Information:

Company Name: TIMBER CREEK OPERATING LLC Company Number: 10672
Address: 1001 17TH STREET #1000
City: DENVER State: CO Zip: 80202

LOCATION - Location ID: 312086

Location Name: HILL RANCH-634S67W Number: 28NWSE County: LAS ANIMAS
Qtrqtr: NWSE Sec: 28 Twp: 34S Range: 67W Meridian: 6
Latitude: 37.053100 Longitude: -104.889060

FACILITY - API Number: 05-071-00 Facility ID: 257550

Facility Name: HILL RANCH Number: 28-10V
Qtrqtr: NWSE Sec: 28 Twp: 34S Range: 67W Meridian: 6
Latitude: 37.053100 Longitude: -104.889060

CORRECTIVE ACTIONS:

1 CA# 119064

Corrective Action: Need to put up lease sign for HR 28-10. Date: 10/27/2018

Response: CA COMPLETED Date of Completion: 10/25/2018

Operator Comment: Timber Creek was unable to locate the lease sign. It was on a portable stand in front of the well head prior to well work. All of the required information was written on the separator door for now. A new sign must be ordered. See the photo log in the attachments for details.

COGCC Decision: Approved pending re-inspection

COGCC
Representative:

2 CA# 119065

Corrective Action: Mark unmarked deadman.

Date: 10/27/2018

Response: CA COMPLETED

Date of Completion: 10/25/2018

Operator
Comment: A post was installed to mark the unmarked deadman anchor.

COGCC Decision: Approved pending re-inspection

COGCC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment: The CA for the lease sign is not 100% corrected, a new lease sign must be ordered. All required lease sign information was written on the door of the separator house.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Edie Fitzgerald

Signed: _____

Title: Sr. Environmental Tech.

Date: 10/25/2018 4:04:22 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
401810445	FIR RESOLUTION SUBMITTED
401810459	Lease sign and deadman anchor marked

Total Attach: 2 Files