

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
403220274

Date Received:
11/07/2022

FIR RESOLUTION FORM

Overall Status:

CA Summary:

3 of 3 CAs from the FIR responded to on this Form

3 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10464

Name of Operator: CATAMOUNT ENERGY PARTNERS LLC

Address: 1001 17TH STREET STE 1160

City: DENVER State: CO Zip: 80202

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

General

Inspections@catamountep.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 700300443

Inspection Date: 10/03/2022

FIR Submit Date: 10/05/2022

FIR Status: _____

Inspected Operator Information:

Company Name: CATAMOUNT ENERGY PARTNERS LLC

Company Number: 10464

Address: 1001 17TH STREET STE 1160

City: DENVER State: CO Zip: 80202

LOCATION - Location ID: 325488

Location Name: PINE RIVER UNIT-M34N6W Number: 31SWSE County: LA PLATA

Qtrqr: SWSE Sec: 31 Twp: 34N Range: 6W Meridian: M

Latitude: 37.142565 Longitude: -107.538958

FACILITY - API Number: 05-067-

-00

Facility ID: 214877

Facility Name: Pine River Unit 3-31

Number: 1

Qtrqr: SWSE Sec: 31 Twp: 34N Range: 6W Meridian: M

Latitude: 37.142565 Longitude: -107.538958

CORRECTIVE ACTIONS:

1 CA# 164993

Corrective Action: Continue clean up, file spill report. Repair liner and minimize and respond to releases during completion operations.

Date: 10/07/2022

Response: CA COMPLETED

Date of Completion: 10/05/2022

Operator
Comment:

Cleaned up location, repaired liner. Filed initial spill report Form #403189984 and subsequent #403198369.

COGCC Decision:

COGCC
Representative:

2 CA# 164995

Corrective Action: Repair/maintain installed BMPs and determine if additional BMPs are needed.

Date: _____

Response: CA COMPLETED

Date of Completion: 11/03/2022

Operator
Comment: Added BMPs to culverts and maintained ditches.

COGCC Decision: _____

COGCC
Representative:

3 CA# 165208

Corrective Action: Repair or replace liner if used for required spill prevention during completion operations.

Date: 10/07/2022

Response: CA COMPLETED

Date of Completion: 10/05/2022

Operator
Comment: Repaired liner prior to completion operations.

COGCC Decision: _____

COGCC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Nolan Redmond

Signed: _____

Title: Geo/Eng Tech

Date: 11/7/2022 8:29:18 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
------------------------	--------------------

403220414	Remediation Photos
-----------	--------------------

Total Attach: 1 Files