

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
403218825

Date Received:
11/03/2022

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

5 of 6 CAs from the FIR responded to on this Form

5 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10611
Name of Operator: LONGS PEAK RESOURCES LLC
Address: 2727 ALLEN PARKWAY SUITE 1850
City: HOUSTON State: TX Zip: 77019

Contact Name and Telephone:
Name: _____
Phone: () _____ Fax: () _____
Email: _____

Additional Operator Contact:

Contact Name	Phone	Email
<u>Brandi Terry</u>	<u>8327480912</u>	<u>brandi.terry@boomtownoil.com</u>

COGCC INSPECTION SUMMARY:

FIR Document Number: 697504024
Inspection Date: 06/16/2022 FIR Submit Date: 07/12/2022 FIR Status: _____

Inspected Operator Information:

Company Name: LONGS PEAK RESOURCES LLC Company Number: 10611
Address: 2727 ALLEN PARKWAY SUITE 1850
City: HOUSTON State: TX Zip: 77019

LOCATION - Location ID: 439459

Location Name: Motu East Number: 2821-8CH County: _____
Qtrqr: SESE Sec: 28 Twp: 12N Range: 65W Meridian: 6
Latitude: 40.972180 Longitude: -104.658350

FACILITY - API Number: 05-123-00 Facility ID: 439459

Facility Name: Motu East Number: 2821-8CH
Qtrqr: SESE Sec: 28 Twp: 12N Range: 65W Meridian: 6
Latitude: 40.972180 Longitude: -104.658350

CORRECTIVE ACTIONS:

1 CA# 163283

Corrective Action: Control and contain spills/releases and clean up per Rule 912.a. Date: 08/09/2022

Response: CA COMPLETED Date of Completion: 07/26/2022

Operator Comment: Stained material around wellhead was cleaned.

COGCC Decision: Approved pending re-inspection

Approved pending re-inspection of this FIR resolution acknowledges the document was received. It is not an

COGCC Representative: acknowledgement that the corrective action has been passed. A field inspection will be conducted at a future date to evaluate compliance with COGCC standards.

2 CA# 163284

Corrective Action: Securely fasten all valves, pipes, fittings, and Production Facilities to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 608.e.

Date: 08/09/2022

Response: CA COMPLETED

Date of Completion: 07/26/2022

Operator Comment: Stained material around wellhead was cleaned.

COGCC Decision: **Not Approved**

COGCC Representative: Operator did not address the corrective action.

3 CA# 163285

Corrective Action: Comply with Rule 1003.e.(2). Operator shall have a certified, professional weed contractor perform the corrective action work and the Operator shall present proof of certification and experience.

Date: 07/26/2022

Response: CA COMPLETED

Date of Completion: 07/26/2022

Operator Comment: The weeds were treated from a previously approved weed contractor employed by Quandary consultants. Attached is the weed treatment memos.

COGCC Decision: Approved pending re-inspection

COGCC Representative: Approved pending re-inspection of this FIR resolution acknowledges the document was received. It is not an acknowledgement that the corrective action has been passed. A field inspection will be conducted at a future date to evaluate compliance with COGCC standards.

5 CA# 163287

Corrective Action: Operator shall redo the revegetation in accordance to Rule 1003. Establish vegetation with total perennial, non-invasive uniform plant cover of at least eighty (80) percent of reference area levels. Use an approved seed mixture provided by the local NRCS. Ensure erosion controls are implemented to stabilize the seeded soil, and continue to monitor and manage this site until the location meets Rule 1003 standards, including stormwater and weed management.

Operator shall provide the seed mixture in the required FIRR response.

Revegetation activities shall be complete no later than 11/21/22 or as soon as environmental conditions will permit.

Date: 11/21/2022

Response: CA COMPLETED

Date of Completion: 10/29/2022

Operator Comment: CB Services completed re seeding the location with the approved seed mixture.

COGCC Decision: Approved pending re-inspection

COGCC Representative: Approved pending re-inspection of this FIR resolution acknowledges the document was received. It is not an acknowledgement that the corrective action has been passed. A field inspection will be conducted at a future date to evaluate compliance with COGCC standards.

6 CA# 163288

Corrective Action: Comply with Rule 1002.f.(2)

Date: 08/09/2022

Response: CA COMPLETED

Date of Completion: 07/26/2022

The culvert was repaired.

Operator _____
Comment:

COGCC Decision: Approved pending re-inspection

COGCC Representative: Approved pending re-inspection of this FIR resolution acknowledges the document was received. It is not an acknowledgement that the corrective action has been passed. A field inspection will be conducted at a future date to evaluate compliance with COGCC standards.

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Brandi Terry

Signed: _____

Title: Regulatory Manager

Date: 11/3/2022 3:07:10 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
403218825	FIR RESOLUTION SUBMITTED
403218832	Corrective Action Photos
403218835	Seeding Mixture

Total Attach: 3 Files