

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

403092190

Date Received:

06/29/2022

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

1 of 1 CAs from the FIR responded to on this Form

1 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10133
Name of Operator: HILCORP ENERGY COMPANY
Address: P O BOX 61229
City: HOUSTON State: TX Zip: 77208

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name	Phone	Email
<u>Jones, Tammy</u>		<u>tajones@hilcorp.com</u>
<u>Shorty, Priscilla</u>		<u>pshorty@hilcorp.com</u>

COGCC INSPECTION SUMMARY:

FIR Document Number: 693904587

Inspection Date: 06/01/2022

FIR Submit Date: 06/16/2022

FIR Status: _____

Inspected Operator Information:

Company Name: HILCORP ENERGY COMPANY Company Number: 10133
Address: P O BOX 61229
City: HOUSTON State: TX Zip: 77208

LOCATION - Location ID: 306932

Location Name: UTE 34-10-M34N10W Number: 30SESE County: LA PLATA
Qtrqtr: SESE Sec: 30 Twp: 34N Range: 10W Meridian: M
Latitude: 37.157550 Longitude: -107.969460

FACILITY - API Number: 05-067- -00 Facility ID: 279981

Facility Name: UTE 34-10 Number: 101R
Qtrqtr: SESE Sec: 30 Twp: 34N Range: 10W Meridian: M
Latitude: 37.157550 Longitude: -107.969460

CORRECTIVE ACTIONS:

1 ☒ CA# 162751

Corrective Action: -Stormwater controls need to be maintained and installed within the northeastern project area where concentrated stormwater flows off of the well pad toward two erosional channels. Corrective action date: 7/16/2022

Date: 07/16/2022

Response: CA COMPLETED Date of Completion: 06/28/2022

Operator Comment: The erosional channeling on the northeastern project area has been filled in where the stormwater is flowing around the cobble. The second erosional feature has also been filled in. We added drainage to divert the stormwater down a more gradual slope off location to prevent any further erosion in these areas. See attached photos.

COGCC Decision: Approved pending re-inspection

COGCC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Priscilla Shorty

Signed: _____

Title: OperationsRegulatory Tech

Date: 6/29/2022 6:00:55 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

Document Number **Description**

403092190	FIR RESOLUTION SUBMITTED
403092191	UTE 34-10 101R_Resolved Photos

Total Attach: 2 Files