

State of Colorado  
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

403133210

Date Received:

08/11/2022

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed  
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10749

Name of Operator: SIMCOE LLC

Address: 1199 MAIN AVE SUITE 101

City: DURANGO State: CO Zip: 81301

Contact Name and Telephone:

Name: \_\_\_\_\_

Phone: ( ) \_\_\_\_\_ Fax: ( ) \_\_\_\_\_

Email: \_\_\_\_\_

Additional Operator Contact:

Contact Name

Phone

Email

General

sjninspections@ikavenergy.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 693904265

Inspection Date: 02/28/2022

FIR Submit Date: 03/04/2022

FIR Status: \_\_\_\_\_

Inspected Operator Information:

Company Name: SIMCOE LLC

Company Number: 10749

Address: 1199 MAIN AVE SUITE 101

City: DURANGO State: CO Zip: 81301

LOCATION - Location ID: 320865

Location Name: LUCHINI 32-6-12-N32N6W Number: 12NESW County: ARCHULETA

Qtrqr: NESW Sec: 12 Twp: 32N Range: 6W Meridian: N

Latitude: 37.029306 Longitude: -107.454209

FACILITY - API Number: 05-007- -00 Facility ID: 205264

Facility Name: LUCHINI 32-6-12 Number: 1

Qtrqr: NESW Sec: 12 Twp: 32N Range: 6W Meridian: N

Latitude: 37.029306 Longitude: -107.454209

CORRECTIVE ACTIONS:

1 ☒ CA# 160001

Corrective Action: -Assess revegetation within the eastern project area during the active growing season, and apply seeding where vegetation is not approaching reclamation requirements. Revegetation needs to be representative of the reference area, and soil testing/treatment should be conducted where needed for vegetation establishment. Corrective action date: 6/1/2022.

Date: 06/01/2022

Response: CA COMPLETED

Date of Completion: 03/28/2022

Operator  
Comment:

The areas indicated for reseeding are outside of pad area and in LO area where they graze cattle.

COGCC Decision: Approved pending re-inspection

COGCC  
Representative:

2 ☒ CA# 160002

Corrective Action: -Stabilization measures need to be applied to stabilize deep rutting and degradation on the access road by 4/4/2022.

Date: 04/04/2022

Response: CA COMPLETED

Date of Completion: 03/28/2022

Operator  
Comment:

Repaired access road and smoothed out ruts on location and removed alkali-stained soils.

COGCC Decision: Approved pending re-inspection

COGCC  
Representative:

#### OPERATOR COMMENT AND SUBMITTAL

Comment: CA complete. See attached photos.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Grace Bryson

Signed: \_\_\_\_\_

Title: Permitting Specialist I

Date: 8/11/2022 11:45:00 AM

### ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
403133210	FIR RESOLUTION SUBMITTED
403133219	Luchini 32-6-12 1, CA Completion Photos

Total Attach: 2 Files