

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

403197546

Date Received:

10/14/2022

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

3 of 3 CAs from the FIR responded to on this Form

3 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10351

Name of Operator: WAPITI OPERATING LLC

Address: 1310 W SAM HOUSTON PKWY N

City: HOUSTON State: TX Zip: 77043

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name Phone

MADISON RANDY

Email

rmadison@wapitienergy.com

Michael Mattorano

mmattorano@wapitienergy.com

Sonny Middlebrook

smiddlebrook@wapitienergy.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 690203454

Inspection Date: 09/23/2022

FIR Submit Date: 09/29/2022

FIR Status: _____

Inspected Operator Information:

Company Name: WAPITI OPERATING LLC

Company Number: 10351

Address: 1310 W SAM HOUSTON PKWY N

City: HOUSTON State: TX Zip: 77043

LOCATION - Location ID: 307701

Location Name: VPR C-635S66W Number: 8NWNE County: LAS ANIMAS

Qtrqr: NWNE Sec: 8 Twp: 35S Range: 66W Meridian: 6

Latitude: 37.015960 Longitude: -104.802100

FACILITY - API Number: 05-071- -00 Facility ID: 89239

Facility Name: VPR C Number: 7

Qtrqr: NWNE Sec: 8 Twp: 35S Range: 66W Meridian: 6

Latitude: 37.015960 Longitude: -104.802100

CORRECTIVE ACTIONS:

1 ☒ CA# 164843

Corrective Action: Comply with Rule 606. Remove tree debris caused by grading operations.

Date: 10/07/2022

Response: CA COMPLETED

Date of Completion: 10/10/2022

Operator Comment: Tree was cut down and removed from the area. See attached photo.

COGCC Decision: Approved pending re-inspection

COGCC
Representative:

2 ☒ CA# 164844

Corrective Action: Maintain in good mechanical condition per Rule 608.e.
Comply with 606.

Date: 10/07/2022

Response: CA COMPLETED

Date of Completion: 10/11/2022

Operator
Comment: Electric line was not energized. It was removed from the location see attached photo.

COGCC Decision: Approved pending re-inspection

COGCC
Representative:

3 ☒ CA# 164845

Corrective Action: Install or repair required BMPs per Rule 1002.f.(2)C

Date: 10/14/2022

Response: CA COMPLETED

Date of Completion: 11/01/2022

Operator
Comment: Rock Checks will be installed by 11/1/2022 to control erosion on the road edges.

COGCC Decision: Approved pending re-inspection

COGCC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Randy L. Madison

Signed: _____

Title: HSE & Reg. Specialist, Sr

Date: 10/14/2022 9:02:52 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
403197546	FIR RESOLUTION SUBMITTED
403197611	Pic #1
403197612	Pic #2

Total Attach: 3 Files