

00107121

RECEIVED

FEB 9 1976



99999999

U.S. CONSERVATION COMMISSION
DEPARTMENT OF NATURAL RESOURCES
STATE OF COLORADO

State for Patented and Federal lands.
State for State lands.

5. LEASE DESIGNATION AND SERIAL NO.
COLO. OIL & GAS CONS. COMM.

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input checked="" type="checkbox"/> Dry		6. IF INDIAN, ALLOTTEE OR TRIBE NAME
2. NAME OF OPERATOR Frank H. Walsh		7. UNIT AGREEMENT NAME
3. ADDRESS OF OPERATOR Box 30, Sterling, Colorado 80751		8. FARM OR LEASE NAME Downing
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) At surface SW NE Section 30-3S-58W		9. WELL NO. 30-2
At proposed prod. zone		10. FIELD AND POOL, OR WILDCAT Wildcat
14. PERMIT NO. 76-7		11. SEC., T., E., M., OR BLK. AND SURVEY OR AREA 30-3S-58W
15. ELEVATIONS (Show whether DF, RT, GR, etc.) 5155 GR		12. COUNTY Adams
		13. STATE Colorado

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
TEST WATER SHUT-OFF <input type="checkbox"/>	PULL OR ALTER CASING <input type="checkbox"/>	WATER SHUT-OFF <input type="checkbox"/>	REPAIRING WELL <input type="checkbox"/>
FRACTURE TREAT <input type="checkbox"/>	MULTIPLE COMPLETE <input type="checkbox"/>	FRACTURE TREATMENT <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
SHOOT OR ACIDIZE <input type="checkbox"/>	ABANDON <input type="checkbox"/>	SHOOTING OR ACIDIZING <input type="checkbox"/>	ABANDONMENT <input checked="" type="checkbox"/>
REPAIR WELL <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	(Other) _____	
(Other) _____		(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)	

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

Date of work January 10, 1976

Plugged and abandoned.
Set 15 sks at base of surface pipe.
Set 10 sks at top of surface and welded steel plate.
Plugging letter attached.

DVR	
FJP	✓
HHM	✓
JAM	✓
JJD	✓
GCH	✓
CGM	



00401378

18. I hereby certify that the foregoing is true and correct

SIGNED J.H. Walsh TITLE Operator DATE 2/5/76

(This space for Federal or State office use)

APPROVED BY D. Rogers TITLE DIRECTOR DATE FEB 10 1976
O & G CONS. COMM.

CONDITIONS OF APPROVAL, IF ANY:

X