

State of Colorado  
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:  
403229194

Date Received:  
11/15/2022

## FIR RESOLUTION FORM

### Overall Status:

#### CA Summary:

3 of 3 CAs from the FIR responded to on this Form

3 CA Completed  
0 Factual Review Request

### OPERATOR INFORMATION

OGCC Operator Number: 10133  
Name of Operator: HILCORP ENERGY COMPANY

Address: P O BOX 61229

City: HOUSTON State: TX Zip: 77208

#### Contact Name and Telephone:

Name: \_\_\_\_\_

Phone: ( ) Fax: ( )

Email: \_\_\_\_\_

#### Additional Operator Contact:

Contact Name

Phone

Email

General

FarmingtonRegulatoryTechs@hilcorp.com

Labowskie, Steve

steve.labowskie@state.co.us

### COGCC INSPECTION SUMMARY:

FIR Document Number: 702500759

Inspection Date: 11/09/2022

FIR Submit Date: 11/09/2022

FIR Status: \_\_\_\_\_

#### Inspected Operator Information:

Company Name: HILCORP ENERGY COMPANY

Company Number: 10133

Address: P O BOX 61229

City: HOUSTON State: TX Zip: 77208

#### LOCATION - Location ID: 326297

Location Name: HUBER-LEWIS-N35N8W Number: 33SWSE County: LA PLATA

Qtrqtr: SWSE Sec: 33 Twp: 35N Range: 8W Meridian: N

Latitude: 37.253760 Longitude: -107.747900

#### FACILITY - API Number: 05-067-00 Facility ID: 216188

Facility Name: HUBER-LEWIS Number: 2-33

Qtrqtr: SWSE Sec: 33 Twp: 35N Range: 8W Meridian: N

Latitude: 37.253760 Longitude: -107.747900

### CORRECTIVE ACTIONS:

1 CA# 166021

Corrective Action: Remove impacted material and dispose of in approved manner per rule 906 and 1002.f.

Date: 11/17/2022

Response: CA COMPLETED

Date of Completion: 11/14/2022

Operator Comment: All impacted material at compressor skid and pump jack has been removed and treated with Simple Green. See attached photos.

COGCC Decision: \_\_\_\_\_

Date: 11/15/2022 5:46:20 AM

## Page 2 of 2