

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
403222821

Date Received:
11/08/2022

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

2 of 3 CAs from the FIR responded to on this Form

2 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10433

Name of Operator: LARAMIE ENERGY LLC

Address: 1700 LINCOLN ST STE 3950

City: DENVER State: CO Zip: 80203

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name	Phone	Email
<u>Devine, Ellice</u>		<u>ellice.whittington@state.co.us</u>
<u>Wheeler, Steven</u>		<u>steven.wheeler@state.co.us</u>
<u>.Laramie</u>		<u>cogccnotifications@laramie-energy.com</u>

COGCC INSPECTION SUMMARY:

FIR Document Number: 696204257

Inspection Date: 10/17/2022

FIR Submit Date: 10/18/2022

FIR Status: _____

Inspected Operator Information:

Company Name: LARAMIE ENERGY LLC

Company Number: 10433

Address: 1700 LINCOLN ST STE 3950

City: DENVER State: CO Zip: 80203

LOCATION - Location ID: 427315

Location Name: Shell Number: 797-03A County: _____

Qtrqr: TCT Sec: 3 Twp: 7S Range: 97W Meridian: 6
71

Latitude: 39.479610 Longitude: -108.202060

FACILITY - API Number: 05-045- -00 Facility ID: 427315

Facility Name: Shell Number: 797-03A

Qtrqr: TCT Sec: 3 Twp: 7S Range: 97W Meridian: 6
71

Latitude: 39.479610 Longitude: -108.202060

CORRECTIVE ACTIONS:

1 CA# 165399

Corrective Action: Conduct additional reclamation on areas of the Location not progressing towards 1003 revegetation standards and requirements. Ensure BMPs are implemented per good engineering practices to stabilize the seeded soils.

Date: 11/30/2022

Response: CA COMPLETED

Date of Completion: 11/07/2022

Operator Comment: We have leveled and reseeded this location

COGCC Decision: Approved pending re-inspection

COGCC Representative: Approved pending re-inspection. Based on photo documentation provided, work to address the corrective action appears to have been performed. A field inspection will be conducted at a future date to evaluate compliance with COGCC rules.

2 CA# 165400

Corrective Action: Comply with Rule 1002.f.(2); implement and maintain required stormwater and erosion control BMPs in accordance with good engineering practices.

Date: 10/25/2022

Response: CA COMPLETED

Date of Completion: 11/07/2022

Operator Comment: We have installed BMPs to address Storm water issues

COGCC Decision: Approved pending re-inspection

COGCC Representative: Approved pending re-inspection. Based on photo documentation provided, work to address the corrective action appears to have been performed. A field inspection will be conducted at a future date to evaluate compliance with COGCC rules.

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Lori Muhr

Signed: _____

Title: Regulatory Specialist

Date: 11/8/2022 1:26:58 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
403222821	FIR RESOLUTION SUBMITTED
403222825	Corrective Action Photos

Total Attach: 2 Files