

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
403057177

Date Received:
05/31/2022

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

4 of 4 CAs from the FIR responded to on this Form

4 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 74165
Name of Operator: RENEGADE OIL & GAS COMPANY LLC
Address: 6155 S MAIN STREET #225
City: AURORA State: CO Zip: 80016

Contact Name and Telephone:
Name:
Phone: () Fax: ()
Email:

Additional Operator Contact:

Contact Name	Phone	Email
COGCC		mike.leonard@state.co.us
Gomez, Jason		jason.gomez@state.co.us
Condill, JB	(303) 680-4725	jbcrog@aol.com
Ingve, Ed	(303) 829-2354	ed@renegadeoilandgas.com
Espinosa, Bill	(303) 829-4982	billespinosa30@yahoo.com
Pesicka, Conor		conor.pesicka@state.co.us

COGCC INSPECTION SUMMARY:

FIR Document Number: 687400863
Inspection Date: 05/16/2022 FIR Submit Date: 05/16/2022 FIR Status:

Inspected Operator Information:

Company Name: RENEGADE OIL & GAS COMPANY LLC Company Number: 74165
Address: 6155 S MAIN STREET #225
City: AURORA State: CO Zip: 80016

LOCATION - Location ID: 320439

Location Name: HOSMER-62S64W Number: 4SENW County:
Qtrqr: SENW Sec: 4 Twp: 2S Range: 64W Meridian: 6
Latitude: 39.907571 Longitude: -104.557701

FACILITY - API Number: 05-001-00 Facility ID: 320439

Facility Name: HOSMER-62S64W Number: 4SENW
Qtrqr: SENW Sec: 4 Twp: 2S Range: 64W Meridian: 6
Latitude: 39.907571 Longitude: -104.557701

CORRECTIVE ACTIONS:

1 CA# 161943

Corrective Action: Follow Rule 603 (i)

Date: 05/23/2022

Response: CA COMPLETED

Date of Completion: 05/23/2022

Operator Comment: Bullplug added to loadline. See attached photo.

COGCC Decision: Approved via an AMI

COGCC Representative:

2 CA# 161944

Corrective Action: 30-days to clean up and remove stained soil.

Date: 06/17/2022

Response: CA COMPLETED

Date of Completion: 05/18/2022

Operator Comment: Stained soil within separator house cleaned up. Stained soil adjacent to separator manifold removed. See attached photos.

COGCC Decision: Approved via an AMI

COGCC Representative:

3 CA# 161945

Corrective Action: Immediately cease venting/flaring. Submit Form 4 for review and approval to vent or flare.

Date: 05/17/2022

Response: CA COMPLETED

Date of Completion: 05/17/2022

Operator Comment: Venting out of the water tank was due to equipment malfunction and personnel communication issues. Instructions have been reiterated to contract personnel. Pressure regulating control equipment has been rebuilt. A new pressure reducing non-venting pressure regulator was added to the well's casing to add redundancy to the gas control system and prevent future venting. See photo.

COGCC Decision: Approved via an AMI

COGCC Representative:

4 CA# 162151

Corrective Action: Submitt gas capture plane to COGCC with in 5 days of recieving this inspection

Date: 05/23/2022

Response: CA COMPLETED

Date of Completion: 05/17/2022

Operator Comment: No routine gas venting is occurring. Produced gas is being metered and sold to a third party Bitcoin mining operator (Datahawk Energy LLC) utilizing electrical generation equipment. Since no venting and flaring is anticipated per normal operations, no Form 4 requesting permission to vent or flare is required per Rule 903.d.(3). Measurement of gas sold to the third party is occurring in order to comply with Rule 903.d.(4).

COGCC Decision: Approved via an AMI

COGCC Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment: All corrective actions are addressed within this FIRR pertaining to a field inspection from 5/16/2022. Gas venting observed was as a result of equipment malfunction and is not done as a part of standard operation. Renegade believes that per rule no gas capture plan or Form 4 is required for the third party onsite gas use for electrical generation.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Edward Ingve

Signed: _____

Title: Manager/Owner

Date: 5/31/2022 8:29:42 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

Document Number	Description
403057177	FIR RESOLUTION SUBMITTED
403062218	Separator shed cleaned up
403062223	Load line bull plug added
403062228	Stained soil adjacent to separator addressed
403062688	Additional control valve placed in service
403062690	Stained soil addressed and separator berm redone

Total Attach: 6 Files