

STATE OF COLORADO
OIL AND GAS CONSERVATION COMMISSION
DEPARTMENT OF NATURAL RESOURCES



00416456

File in duplicate for Patented and Federal lands.
File in triplicate for State lands.

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.)

Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>		5. LEASE DESIGNATION & SERIAL NO. Fee	
2. NAME OF OPERATOR E. Doyle Huckabay, Ltd.		6. IF INDIAN, ALLOTTEE OR TRIBE NAME -----	
3. ADDRESS OF OPERATOR 1706 Security Life Bldg., Denver, CO		7. UNIT AGREEMENT NAME -----	
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) At surface 660' FSL, 1780 FEL, Sec. 22, T35-R59W SW/4SE/4 At proposed prod. zone Same as surface		8. FARM OR LEASE NAME L & L Land Company	
14. PERMIT NO. 84-486		9. WELL NO. 1-22	
15. ELEVATIONS (Show whether DF, RT, GR, etc.) 5097GR		10. FIELD AND POOL, OR WILDCAT Noonen-Ranch	
		11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA 22: T35-R59W	
		12. COUNTY Adams	13. STATE CO

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

TEST WATER SHUT-OFF

☐
☐
☐
☐

PULL OR ALTER CASING

☐
☐
☒
☐

FRACTURE TREAT

MULTIPLE COMPLETE

SHOOT OR ACIDIZE

ABANDON

REPAIR WELL,

CHANGE PLANS

(Other)

WATER SHUT-OFF

☐
☐
☐

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

18. Date of work 07-11-88

* Must be accompanied by a cement verification report.

Run sand from 6245 to 6100. Dump 5 sks. cement on top sand. Fill hole with mud. Cut 5½" casing off @ 3500'. Pump 35 sks. cement in and out of 9-5/8" surface pipe set @ 332', set surface plug of 5 sks. cement. Cut off casing 4' below surface, weld on plate.

FOR OFFICE
FILE
JUN 27 1988
JUN 27 1988
JUN 27 1988

RECEIVED
JUN 27 1988
COLO. OIL & GAS CONS. COMM.

19. I hereby certify that the foregoing is true and correct

SIGNED

Nat. G. Goodwin

TITLE

Agent

DATE

06-23-88

(This space for Federal or State office use)

APPROVED BY

H. A. [Signature]

TITLE

SUPR. PETROLEUM ENGINEER
Oil & Gas Cons. Comm.

DATE

JUL 05 1988

CONDITIONS OF APPROVAL, IF ANY: