

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

402275331

Date Received:

12/31/2019

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

6 of 6 CAs from the FIR responded to on this Form

6 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10464

Name of Operator: CATAMOUNT ENERGY PARTNERS LLC

Address: 1001 17TH STREET STE 1160

City: DENVER State: CO Zip: 80202

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

Inspections, All

inspections@catamountep.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 687905509

Inspection Date: 09/18/2019

FIR Submit Date: 09/20/2019

FIR Status: _____

Inspected Operator Information:

Company Name: CATAMOUNT ENERGY PARTNERS LLC

Company Number: 10464

Address: 1801 BROADWAY #1000

City: DENVER State: CO Zip: 80202

LOCATION - Location ID: 320863

Location Name: PARGIN MOUNTAIN UNIT Number: M34N5W /34NESW County: ARCHULETA

Qtrqr: NESW Sec: 34 Twp: 34N Range: 5W Meridian: M

Latitude: 37.146900 Longitude: -107.382320

FACILITY - API Number: 05-007- -00 Facility ID: 205261

Facility Name: PARGIN MOUNTAIN UNIT Number: 11

Qtrqr: NESW Sec: 34 Twp: 34N Range: 5W Meridian: M

Latitude: 37.146900 Longitude: -107.382320

CORRECTIVE ACTIONS:

1 ☒ CA# 130989

Corrective Action: Contact SW reclamation specialist about topsoil storage.

Date: 10/09/2019

Response: CA COMPLETED

Date of Completion: 11/18/2019

Operator Comment: Slope has been reclaimed and top soil seeded. Weeds have been removed.

COGCC Decision: Approved pending re-inspection

COGCC
Representative:

2 ☒ CA# 130990

Corrective Action: Install erosion controls along western cut slope to comply with Rule 1002 and COA and best management practices.

Date: _____

Response: CA COMPLETED

Date of Completion: 11/08/2019

Operator
Comment: Cut-Slopes have been reclaimed

COGCC Decision: Approved pending re-inspection

COGCC
Representative:

3 ☒ CA# 130991

Corrective Action: Prevent unused equipment and debris from being stored in accumulated stormwater.

Date: 10/03/2019

Response: CA COMPLETED

Date of Completion: 12/01/2019

Operator
Comment: Equipment has been removed

COGCC Decision: Approved pending re-inspection

COGCC
Representative:

4 ☒ CA# 130992

Corrective Action: Remove all debris to comply with Interim Reclamation Rule 1003.a.

Date: 11/30/2019

Response: CA COMPLETED

Date of Completion: 11/04/2019

Operator
Comment: Removed all debris.

COGCC Decision: Approved pending re-inspection

COGCC
Representative:

5 ☒ CA# 130993

Corrective Action: Remove all pipe and equipment to comply with Interim Reclamation Rule 1003.a.

Date: 11/30/2019

Response: CA COMPLETED

Date of Completion: 12/01/2019

Operator
Comment: Removed all pipe and equipment.

COGCC Decision: Approved pending re-inspection

COGCC
Representative:

6 ☒ CA# 130994

Corrective Action: Install wildlife protection around wellhead to comply with Rule 1003.a.

Date: 11/30/2019

Response: CA COMPLETED

Date of Completion: 11/01/2019

Cellars backfilled with sand.

Approved pending re-inspection

--

OPERATOR COMMENT AND SUBMITTAL	

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Nolan Redmond

Geo/Eng Tech

Date: 12/31/2019 2:38:33 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
402275331	FIR RESOLUTION SUBMITTED
402275342	Remedial Report

Total Attach: 2 Files