

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

403244130

Date Received:

11/30/2022

FIR RESOLUTION FORM

Overall Status:

CA Summary:

1 of 3 CAs from the FIR responded to on this Form

0 CA Completed

1 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10433

Name of Operator: LARAMIE ENERGY LLC

Address: 1700 LINCOLN ST STE 3950

City: DENVER State: CO Zip: 80203

Contact Name and Telephone:

Name: _____

Phone: () Fax: ()

Email: _____

Additional Operator Contact:

Contact Name Phone

Bankert, Wayne

Email

wbankert@laramie-energy.com

Deranleau, Greg

greg.deranleau@state.co.us

Longworth, Mike

michael.longworth@state.co.us

Fischer, Alex

alex.fischer@state.co.us

Laramie

cogccnotifications@laramie-energy.com

Hughes, Jim

jimo.hughes@state.co.us

Chris, Clark

cclark@Laramie-Energy.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 698100280

Inspection Date: 11/28/2022

FIR Submit Date: 11/29/2022

FIR Status: _____

Inspected Operator Information:

Company Name: LARAMIE ENERGY LLC

Company Number: 10433

Address: 1700 LINCOLN ST STE 3950

City: DENVER State: CO Zip: 80203

LOCATION - Location ID: 449070

Location Name: Gunderson Number: 20-03 Pad County: _____

Qtrqr: NENW Sec: 20 Twp: 9S Range: 93W Meridian: 6

Latitude: 39.266756 Longitude: -107.795281

FACILITY - API Number: 05-077-00 Facility ID: 449070

Facility Name: Gunderson Number: 20-03 Pad

Qtrqr: NENW Sec: 20 Twp: 9S Range: 93W Meridian: 6

Latitude: 39.266756 Longitude: -107.795281

CORRECTIVE ACTIONS:

3 CA# 166297

Corrective Action: Submit a Form 15 Pit Report for construction of emergency pits within 30 days of construction, per Rule 908.c.(1).

Date: 12/22/2022

Response: FACTUAL REVIEW REQUEST

Basis for Review: Corrective action dates are not attainable

Operator Comment: In order to prevent fluids from reaching Buzzard Creek, Laramie excavated two recovery trenches roughly parallel to the stream bank to capture water and prevent continued influx to Buzzard Creek. Trench Number 1(Photo 4 in inspection) was 25 feet in length, 1.5 feet (Backhoe Bucket) wide, and 12-15 inches deep. Trench Number 2(Photo 5 in inspection) was 35 feet in length, 1.5 feet wide, and 12-15 inches deep. Each trench then collected water allowing for water trucks to pump and haul to Laramie Harrison Creek Water Treatment Facility (441237).

Soil samples were collected from the trench walls to insure no contamination is present prior to back filling the trenches.

Laramie contends the recovery trenches should not be labelled as emergency pits.

COGCC Decision:

COGCC Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Lori Muhr

Signed:

Title: Regulatory Specialist

Date: 11/30/2022 10:22:16 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
------------------------	--------------------

--	--

Total Attach: 0 Files