

STATE OF COLORADO
OIL AND GAS CONSERVATION COMMISSION
DEPARTMENT OF NATURAL RESOURCES



RECEIVED

MAR 21 1985

File in duplicate for Patented and Federal lands.
File in triplicate for State lands.

5. LEASE DESIGNATION & SURFACE NO.

6. IF INDIAN LAND, STATE OR TRIBE NAME
COLO. OIL & GAS CONSERV. COMM.

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

UPRR 56 Amoco "E" (228)

9. WELL NO.

1

10. FIELD AND POOL, OR WILDCAT

Lonetree

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA

Sec. 31 - T3S - R59W

12. COUNTY

Adams

13. STATE

CO

1. OIL WELL GAS WELL OTHER P x A former producer

2. NAME OF OPERATOR

Amoco Production Company

3. ADDRESS OF OPERATOR

P.O. Box 39200 - Denver, CO 80239

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.
See also space 17 below.)

At surface 660' FEL, 2160' FSL SE/4 SE/4 Sec. 31
At proposed prod. zone

9

14. PERMIT NO.

75-30

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

5011' GR

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

TEST WATER SHUT-OFF

PULL OR ALTER CASING

WATER SHUT-OFF

REPAIRING WELL

FRACTURE TREAT

MULTIPLE COMPLETE

FRACTURE TREATMENT

ALTERING CASING

SHOOT OR ACIDIZE

ABANDON

SHOOTING OR ACIDIZING

ABANDONMENT*

REPAIR WELL

CHANGE PLANS.

(Other)

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

18. Date of work January 8, 1985

* Must be accompanied by a cement verification report.

PxA; Abandonment

Remarks: 1st plug: Set CIBP at 6100' with 5 sacks cement.
2nd plug: Pump 40 sacks - plug: 2500-2350'.
3rd plug: Pump 20 sacks - plug: 410-335'.
4th plug: Pump 10 sacks - plug to surface; PxA
Cut casing 5' below ground level and weld on cap.
Restore location to original contour.

1985	
JAN	
FEB	
MAR	
APR	
MAY	
JUN	
JUL	
AUG	
SEP	
OCT	
NOV	
DEC	

Exhausted oil well

Verbal approval by Hack Morrell, OGCC, to Scott Robinson, Amoco, 9-25-84.

19. I hereby certify that the foregoing is true and correct

SIGNED

H.R. West

DISTRICT ADMINISTRATIVE SUPERVISOR

DATE 3-20-85

(This space for Federal or State office use)

APPROVED BY

William R. Smith

TITLE

DIRECTOR
O & G Cons. Comm.

DATE

APR - 5 1985

CONDITIONS OF APPROVAL, IF ANY:

F