



Oil-Water Spill/Complaint Inspection Form

Location 1 1/2 miles NE of CABIN CREEK  
SW SW 29-35-59N Field 1 met res  
Operator HUCKABAY? County ADAMS  
Well Name Peterson API # \_\_\_\_\_

Person calling/sending in complaint: FLOYD LINNEBUR  
Date of occurrence: 1/2/91  
Date of complaint: 1/2/91  
Phone#: 1-822-5833

Follow up by phone: Date 1-3-91 Contact Gayle w/ Huckabay 534-0763 she will contact up many and plan to re plug. Then contact OGCC. EBB  
Follow up by field visit: Date \_\_\_\_\_ Contact \_\_\_\_\_

Type of fluid spill/overflow: \_\_\_\_\_  
Estimated volume of fluid: \_\_\_\_\_  
Area effected: \_\_\_\_\_  
Did spill/overflow reach waters of the state? Yes \_\_\_\_\_ No \_\_\_\_\_  
Remedial action: Sundry notice required - Yes \_\_\_\_\_ No \_\_\_\_\_  
(Rule 329) How was spill/overflow cleaned up? \_\_\_\_\_

Comments:

LEAKING H<sub>2</sub>O OUT OF DRY HOLE,  
DRUG PITZ NEVER CLOSED.  
"SLOW TRICKLE" + BUBBLING GAS  
RUNNING CATTLE IN PASTURE.

1/2/91

UJK

SW SE 4

Tiber Mike well, CSG sucks out of ground  
HAS 4 wells like THIS

Huckabay pumpset  
Dick Comer - Ft Morgan -  
mut Goodwin - Tyler, TX

Jim

Wouter Leeling

1-3-90

Called Huckabay 1-3-90. they will  
evaluate.

1-4-90 -

Nat Goodwin - Huckabay miru

on 2-29 29-35 59W

Petersen

BB

will plug at 40 sxc shoe  
300-250 10 sxc; well cap.

Pat Hanks 769-4711



460 9318