

State of Colorado  
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:  
403254828

Date Received:  
12/08/2022

FIR RESOLUTION FORM

Overall Status:

CA Summary:

1 of 1 CAs from the FIR responded to on this Form

1 CA Completed  
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 96850

Name of Operator: TEP ROCKY MOUNTAIN LLC

Address: 1058 COUNTY ROAD 215

City: PARACHUTE State: CO Zip: 81635

Contact Name and Telephone:

Name: \_\_\_\_\_

Phone: ( ) Fax: ( )

Email: \_\_\_\_\_

Additional Operator Contact:

Contact Name

Phone

Email

TEP

COGCCInspectionReports@terraep.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 702800969

Inspection Date: 11/23/2022

FIR Submit Date: 11/30/2022

FIR Status: \_\_\_\_\_

Inspected Operator Information:

Company Name: TEP ROCKY MOUNTAIN LLC

Company Number: 96850

Address: 1058 COUNTY ROAD 215

City: PARACHUTE State: CO Zip: 81635

LOCATION - Location ID: 334748

Location Name: WELLS-66S94W Number: 32NESW County: \_\_\_\_\_

Qtrqr: NESW Sec: 32 Twp: 6S Range: 94W Meridian: 6

Latitude: 39.480934 Longitude: -107.912989

FACILITY - API Number: 05-045-00 Facility ID: 334748

Facility Name: WELLS-66S94W Number: 32NESW

Qtrqr: NESW Sec: 32 Twp: 6S Range: 94W Meridian: 6

Latitude: 39.480934 Longitude: -107.912989

CORRECTIVE ACTIONS:

1 CA# 166326

Corrective Action: Control and contain spill.

Date: 11/24/2022

Response: CA COMPLETED

Date of Completion: 12/06/2022

Operator Comment: Chemical supply contractor responded and sucked out all fluid from containment. Packing on pump was replaced and all fittings were checked / tightened. Small drip has been fixed. Operator will continue to monitor during future sight visits. This corrective action has been completed.

COGCC Decision: \_\_\_\_\_

COGCC  
Representative: \_\_\_\_\_

**OPERATOR COMMENT AND SUBMITTAL**

Comment: Chemical supply contractor responded and sucked out all fluid from containment. Packing on pump was replaced and all fittings were checked / tightened. Small drip has been fixed. Operator will continue to monitor during future sight visits. This corrective action has been completed.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Michael Gardner

Signed: \_\_\_\_\_

Title: TEP Environmental Lead

Date: 12/8/2022 2:46:05 PM

**ATTACHMENT LIST**

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<b><u>Document Number</u></b>	<b><u>Description</u></b>
-------------------------------	---------------------------

--	--

Total Attach: 0 Files