

State of Colorado  
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:  
403254886

Date Received:  
12/08/2022

FIR RESOLUTION FORM

Overall Status:

CA Summary:

1 of 4 CAs from the FIR responded to on this Form

1 CA Completed  
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 96850  
Name of Operator: TEP ROCKY MOUNTAIN LLC  
Address: 1058 COUNTY ROAD 215  
City: PARACHUTE State: CO Zip: 81635

Contact Name and Telephone:  
Name:  
Phone: ( ) Fax: ( )  
Email:

Additional Operator Contact:

Contact Name	Phone	Email
Ramsey, Scott		scott.ramsey@state.co.us
TEP		COGCCInspectionReports@terraep.com
Kellerby, Shaun		shaun.kellerby@state.co.us

COGCC INSPECTION SUMMARY:

FIR Document Number: 702800968  
Inspection Date: 11/23/2022 FIR Submit Date: 12/05/2022 FIR Status:

Inspected Operator Information:

Company Name: TEP ROCKY MOUNTAIN LLC Company Number: 96850  
Address: 1058 COUNTY ROAD 215  
City: PARACHUTE State: CO Zip: 81635

LOCATION - Location ID: 311677

Location Name: HARRIS-67S94W Number: 5SWNE County:  
Qtrqr: SWNE Sec: 5 Twp: 7S Range: 94W Meridian: 6  
Latitude: 39.468371 Longitude: -107.910263

FACILITY - API Number: 05-045-00 Facility ID: 311677

Facility Name: HARRIS-67S94W Number: 5SWNE  
Qtrqr: SWNE Sec: 5 Twp: 7S Range: 94W Meridian: 6  
Latitude: 39.468371 Longitude: -107.910263

CORRECTIVE ACTIONS:

2 CA# 166403

Corrective Action: Install proper guy line markers per Rule 1003.a or remove anchors if unnecessary equipment.

Date: 12/14/2022

Response: CA COMPLETED

Date of Completion: 12/07/2022

Operator Comment: TEP production personnel located and marked four guy line anchors on 12/07/22. The Field Inspection Report states that 6 anchors required marking, but the inspection photos only show 3 anchors. If additional anchors are found, TEP will mark those as well. TEP has marked all anchors that could be located. This corrective action is

complete.

COGCC Decision: \_\_\_\_\_

COGCC  
Representative:

--

**OPERATOR COMMENT AND SUBMITTAL**

Comment: TEP production personnel located and marked four guy line anchors on 12/07/22. The Field Inspection Report states that 6 anchors required marking, but the inspection photos only show 3 anchors. If additional anchors are found, TEP will mark those as well. TEP has marked all anchors that could be located. This corrective action is complete.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Michael Gardner

Signed: \_\_\_\_\_

Title: TEP Environmental Lead

Date: 12/8/2022 3:01:12 PM

**ATTACHMENT LIST**

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

**Document Number**      **Description**

<u>Document Number</u>	<u>Description</u>

Total Attach: 0 Files