

State of Colorado  
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:  
403212370

Date Received:  
10/28/2022

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

1 of 1 CAs from the FIR responded to on this Form

1 CA Completed  
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10670  
Name of Operator: MALLARD EXPLORATION LLC  
Address: 1400 16TH STREET SUITE 300  
City: DENVER State: CO Zip: 80202

Contact Name and Telephone:  
Name: \_\_\_\_\_  
Phone: ( ) \_\_\_\_\_ Fax: ( ) \_\_\_\_\_  
Email: \_\_\_\_\_

Additional Operator Contact:

Contact Name	Phone	Email
<u>Mathews, Erin</u>	<u>970-302-6171</u>	<u>emathews@mallardexploration.com</u>
<u>DYK, DUSTIN</u>	<u>720-543-7954</u>	<u>ddyk@mallardexploration.com</u>

COGCC INSPECTION SUMMARY:

FIR Document Number: 696105541  
Inspection Date: 10/11/2022 FIR Submit Date: 10/21/2022 FIR Status: \_\_\_\_\_

Inspected Operator Information:

Company Name: MALLARD EXPLORATION LLC Company Number: 10670  
Address: 1400 16TH STREET SUITE 300  
City: DENVER State: CO Zip: 80202

LOCATION - Location ID: 447902

Location Name: Shull Pad Number: 9-59-31-NENW County: \_\_\_\_\_  
Qtrqtr: NENW Sec: 31 Twp: 9N Range: 59W Meridian: 6  
Latitude: 40.711378 Longitude: -104.022585

FACILITY - API Number: 05-123-00 Facility ID: 447902

Facility Name: Shull Pad Number: 9-59-31-NENW  
Qtrqtr: NENW Sec: 31 Twp: 9N Range: 59W Meridian: 6  
Latitude: 40.711378 Longitude: -104.022585

CORRECTIVE ACTIONS:

1  CA# 165608

Corrective Action: Comply with Rule 1002.f.(2) to install BMPs in accordance with good engineering practices.

Date: 10/11/2022

Corrective action date is the date the locaiton was observed out of compliance.

Response: CA COMPLETED

Date of Completion: 10/28/2022

A dirt berm was added to the top of pulled back pad along the eastern and southeastern edges to prevent

Operator Comment: sediment discharge and any associated rill erosion has been repaired. Bare areas of vegetation have been reseeded and straw mulched. Refer to uploaded photos.

COGCC Decision: Approved pending re-inspection

COGCC Representative: Approved pending re-inspection of this FIR resolution acknowledges the document was received. It is not an acknowledgement that the corrective action has been passed. A field inspection will be conducted at a future date to evaluate compliance with COGCC standards.

OPERATOR COMMENT AND SUBMITTAL

Comment: Per the request, Mallard will submit a Form 4 Interim Reclamation Complete notice when the location meets Rule 1003 standards

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Erin Mathews

Signed: \_\_\_\_\_

Title: VP Development

Date: 10/28/2022 4:38:40 PM

### ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
403212370	FIR RESOLUTION SUBMITTED
403212373	Photos

Total Attach: 2 Files