



**COLORADO OIL & GAS CONSERVATION COMMISSION**  
**FIELD INSPECTION REPORT**



<input type="checkbox"/> NOTICE OF UNSATISFACTORY INSPECTION		1120 Lincoln Street, Suite 801	
<input checked="" type="checkbox"/> NOTICE OF SATISFACTORY INSPECTION		Denver, CO 80203	
		(303)894-2100	
API No. 05- 001 - 9343		LEASE NAME: Maddern	
LOCATION: NESE 22-35-58W		OPERATOR: Western Op.	
DATE: 1-14-97		INSPECTOR: EBB	
Insp. Type: CA	Insp. Status: DA	PA: Y <input checked="" type="radio"/> N	Pass/Fail: P <input checked="" type="radio"/> F
		Viol.: Y <input checked="" type="radio"/> N	NOV: Y <input checked="" type="radio"/> N

INSPECTION ITEM	COMMENTS	INPUT
<b>Well ID Signs</b> (Rule 210, 604.c(4))	✓	
<b>Pits (Reserve/Production)</b> (Rule 902, 903, 904, 905)	R-pit open	
<b>Fences</b> (Rule 603.b.7, 604.C.(3), 1002.A)		
<b>Tank Battery Equipment</b> (Rule 603.b.3, 604)		
<b>Fire Walls/Berms/Dikes</b> (Rule 603.b.12, 604)		
<b>General Housekeeping</b> (Rule 603)	OK	
<b>Spills (Oil/Water)</b> (Rule 907)		
<b>Bradenhead</b> (Rule 207.b)		
<b>Drilling Well/Workover</b> (Rule 317)	Ashby Drlg Cementers Inc.	
<b>Surface Rehabilitation</b> (Rule 1002, 1003, 1004, 1103)	Cultivated area	
<b>Miscellaneous</b>	Access via N. Roman Nose Field from Hwy 36.	

<b>CORRECTIVE ACTION REQUIRED:</b> Close pit per Rule 1003-	
Date Corrective Action Required By: 1-15-97	Date Remedied:

This report is a Notice of Inspection. The Commission requires that you correct any deficiencies shown on this report in a timely manner. Failure to comply may result in enforcement action by the Commission.

