



99999999

OIL & GAS CONSERVATION COMMISSION
FIELD INSPECTION REPORT☒ NOTICE OF UNSATISFACTORY INSPECTION
☐ NOTICE OF SATISFACTORY INSPECTION1120 Lincoln Street, Suite 801
Denver, CO 80203
(303)894-2100

API No. 05- 001 - 5040		LEASE NAME: UPRR-Norven 1B	
LOCATION: SEW 13-35-59W		OPERATOR: Walsh	
DATE: 5-18-97		INSPECTOR: EBB	
Insp. Type: SR	Insp. Status: PA	PA: Y <input checked="" type="radio"/> N <input checked="" type="radio"/>	Pass/Fail: P <input checked="" type="radio"/> F <input checked="" type="radio"/>
		Viol.: Y <input checked="" type="radio"/> N <input checked="" type="radio"/>	NOV: Y <input type="radio"/> N <input type="radio"/>

INSPECTION ITEM

COMMENTS

INPUT

Well ID Signs (Rule 210, 604.c(4))	none	
Pits (Reserve/Production) (Rule 902, 903, 904, 905)		
Fences (Rule 603.b.7, 604.C.(3), 1002.A)		COGCC JUL 10 97
Tank Battery Equipment (Rule 603.b.3, 604)	Cement base, risers	
Fire Walls/Berms/Dikes (Rule 603.b.12, 604)		
General Housekeeping (Rule 603)		
Spills (Oil/Water) (Rule 907)		
Bradenhead (Rule 207.b)		
Drilling Well/Workover (Rule 317)		
Surface Rehabilitation (Rule 1002, 1003, 1004, 1103)	grassland (Arroyo near site)	
Miscellaneous	site - grass covered	

RECEIVED

CORRECTIVE ACTION REQUIRED: Comply with Rule 1004,
remove junk, restore site.

Date Corrective Action Required By: 6-30-97

Date Remedied:

This report is a Notice of Inspection. The Commission requires that you correct any deficiencies shown on this report in a timely manner. Failure to comply may result in enforcement action by the Commission.



00230264