

allison drilling

DRILLING CONTRACTORS SINCE 1910
OIL, GAS & MINERAL DRILLING

June 15, 1993



Eddie B. Binkley
Petroleum Engineer
Colo. Oil and Gas Cons. Comm.
Suite 380, Logan Tower Bldg.
1580 Logan Street
Denver, CO 80203

RECEIVED

JUN 16 1993

COLO. OIL & GAS CONS. COMM.

Re: Sellman-Rico #1, SE SW 32-3S-59W, Adams County, Colorado

Dear Mr. Binkley:

In reference to your letter of May 19th and our prior telephone conversations concerning the leaking plug on the above well, please find attached Form 4 which concerns the replugging of this well.

After receiving your letter I had Early Zion, our toolpusher that originally drilled this well, go to the field to meet with Mr. Harry Hanks. After examining the top of the surface he determined that the well was making a small amount of water. A few days later he returned to the well and lowered a weight on the bottom of a rope and found a cement plug at 147'. Evidently the top plug had slipped down the casing and it rests on the top of the bottom plug that we placed at the bottom of the casing. He also obtained a sample of the water which we sent to Halliburton for analysis (copy enclosed).

It is our recommendation that we run tubing to 147', displace the water, and cement with 150 sack which will place cement from 147' to the top of the surface. At that time we would weld a cap on the top of the surface pipe.

If this procedure is satisfactory with you please approve our Form 4 and we will attempt to accomplish this work in the first half of July.

Very truly yours,

ALLISON DRILLING COMPANY, INC.


J. W. ALLISON, PRESIDENT/CEO

JWA/kb
Enc.