

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
403213075

Date Received:
10/31/2022

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10651
Name of Operator: VERDAD RESOURCES LLC
Address: 1125 17TH STREET SUITE 550
City: DENVER State: CO Zip: 80202

Contact Name and Telephone:
Name: _____
Phone: () _____ Fax: () _____
Email: _____

Additional Operator Contact:

Contact Name	Phone	Email
<u>CUGNETTI, MIKE</u>	<u>720-845-6901</u>	<u>mcugnetti@verdadoil.com</u>

COGCC INSPECTION SUMMARY:

FIR Document Number: 696105543
Inspection Date: 10/11/2022 FIR Submit Date: 10/21/2022 FIR Status: _____

Inspected Operator Information:

Company Name: VERDAD RESOURCES LLC Company Number: 10651
Address: 1125 17TH STREET SUITE 550
City: DENVER State: CO Zip: 80202

LOCATION - Location ID: 441041

Location Name: Martin Number: 3030-3031 County: _____
Qtrqr: SWS Sec: 30 Twp: 9N Range: 59W Meridian: 6
W
Latitude: 40.715188 Longitude: -104.028654

FACILITY - API Number: 05-123-00 Facility ID: 441041

Facility Name: Martin Number: 3030-3031
Qtrqr: SWS Sec: 30 Twp: 9N Range: 59W Meridian: 6
W
Latitude: 40.715188 Longitude: -104.028654

CORRECTIVE ACTIONS:

1 CA# 165609

Corrective Action: Comply with Rule 606 and remove concrete debris. Date: 10/11/2022
Corrective action date is the date the location was observed out of compliance.

Response: CA COMPLETED Date of Completion: 10/27/2022

Operator Comment: concrete debris removed. See attachments for Corrective Action photo documentation.

COGCC Decision: Approved pending re-inspection

COGCC Representative: Approved pending re-inspection of this FIR resolution acknowledges the document was received. It is not an acknowledgement that the corrective action has been passed. A field inspection will be conducted at a future date to evaluate compliance with COGCC standards.

2 CA# 165610

Corrective Action: Comply with Rule 1002.f.(2) to install BMPs in accordance with good engineering practices.

Date: 10/11/2022

Corrective action date is the date the location was observed out of compliance.

Response: CA COMPLETED

Date of Completion: 10/25/2022

Operator Comment: Straw wattles in the southeast corner of the location have been re-installed with trenching and staking and rill erosion area has been compacted. See attachments for Corrective Action photo documentation.

COGCC Decision: Approved pending re-inspection

COGCC Representative: Approved pending re-inspection of this FIR resolution acknowledges the document was received. It is not an acknowledgement that the corrective action has been passed. A field inspection will be conducted at a future date to evaluate compliance with COGCC standards.

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Michael Cugnetti

Signed: _____

Title: Director of EHS&R

Date: 10/31/2022 12:05:50 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
403213075	FIR RESOLUTION SUBMITTED
403213210	Corrective Action Photo Documentation
403213212	Corrective Action Photo Documentation
403213215	Corrective Action Photo Documentation
403213217	Corrective Action Photo Documentation

Total Attach: 5 Files