

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

12/30/2022

Submitted Date:

12/30/2022

Document Number:

690203743

FIELD INSPECTION FORM

Loc ID 309492 Inspector Name: COSTA, RYAN On-Site Inspection 2A Doc Num: _____

Operator Information:

OGCC Operator Number: 10758
Name of Operator: OGRIS OPERATING LLC
Address: PO BOX 53467
City: MIDLAND State: TX Zip: 79710

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Findings:

- 4 Number of Comments
- 2 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
BACA DAVID		dbaca@ogrisop.com	
WARD, GIENA		gward@ogrisop.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
296156	WELL	PR	09/11/2008	CBM	071-09604	NEW ELK 25-10-2	RI

General Comment:

[This is a location inspection.](#)
[See attached photos and additional details within this report.](#)

Location

Lease Road:			
Type	Main		
comment:			
Corrective Action			Date:

Overall Good:

Signs/Marker:			
Type	WELLHEAD		
Comment:			
Corrective Action:			Date:

Emergency Contact Number:			
Comment:	<input type="text"/>		
Corrective Action:	<input type="text"/>		Date: _____

Overall Good:

Spills:			
Type	Area	Volume	
Comment:	There are stained soils at the meter shed.		
Corrective Action:	Control and contain spills/releases and clean up per Rule 912.a. Securely fasten all valves, pipes, fittings, and Production Facilities to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 608.e.		Date: <u>01/03/2023</u>

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:			
Type	PIT		
Comment:	The electric fence is in disrepair around the pit. A more robust fencing should be installed.		
Corrective Action:	Comply with the fencing requirements per the 1002a rules		Date: <u>01/13/2023</u>

Venting:			
Yes/No			
Comment:			
Corrective Action:			Date:

Flaring:			
Type			
Comment:			
Corrective Action:			Date:

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
690203744	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5965259

