



March 17, 1959

Mr. Herbert L. Goldstein  
309 Colorado Commercial and Savings Bank Bldg.  
Colorado Springs, Colo.

Dear Mr. Goldstein:

I am sorry that I was unable to meet with you when I was in the Springs yesterday, following my investigation of the Voltz #1 well in Section 12, 16 South, 66 West.

As you will recall, I visited the location with you in August 1957, and we discussed plugging procedures which you said would be done shortly. On reviewing the well location yesterday, I found it to be in exactly the same condition as when you and I were there. Since this matter seems to be out of hand, please be advised that the well must be plugged prior to April 15, 1959, or the violation will be brought to the attention of my superiors for appropriate action.

Please advise this office two days before the well is to be plugged, so that we may have a witness on the location if we so desire.

Yours very truly,

OIL AND GAS CONSERVATION COMMISSION

---

William R. Smith, Senior Petroleum Engineer

WRS:cm