

Location

Lease Road:			
Type			
comment:	unable to access location due to land owners lock, and previously asked to leave property.		
Corrective ActionL			Date:

Overall Good:

Emergency Contact Number:

Comment:	<input style="width: 100%;" type="text"/>		
Corrective Action:	<input style="width: 100%;" type="text"/>		Date: _____

Overall Good:

Spills:				
Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:			
Type	WELLHEAD		
Comment:	Red AG fencing		
Corrective Action:			Date:

Equipment:			corrective date
Type: Plunger Lift	# 1		
Comment:			
Corrective Action:			Date:
Type: Bradenhead	# 1		
Comment:	Plumbed to surface		
Corrective Action:			Date:

Venting:			
Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:			
Type			
Comment:			
Corrective Action:			Date:

Inspected Facilities

Facility ID: 242324 Type: WELL API Number: 123-10115 Status: SI Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment:

Corrective Action: Date: _____

BradenHead

Date of Last Brhd Test: 07/06/2021 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: _____

End Surf Csg Pressure: 0

Comment:

Corrective Action: Date: _____

COGCC Comments

Comment	User	Date
This inspection does not nullify any orders or NOAV from the COGCC. This site is part of an ongoing investigation for flowline issues. At time of inspection weather conditions were cold, calm, overcast.	medinaj	12/28/2022

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699504352	inspection pictures	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5968789