



Sunburst, Inc.  
Henderson #1

Inspection Document # 696304521

Corrective Action: Install sign to comply with Rule 605.h.