



February 13, 1964

Mr. E. N. Dunlap
California Oil Company
P.O. Box 780
Denver, Colorado 80201

Dear Mr. Dunlap:

Your prompt reply to the matter of the recompletion of the G. L. King No. 2 well, 22-8N-66W, Pierce field, Colorado, was greatly appreciated, and as far as we are concerned, there is no question that the job was accomplished.

I have enclosed a copy of my letter to Mr. Lesh, who made the inquiry.

Very truly yours,

OIL AND GAS CONSERVATION COMMISSION

William R. Smith, Deputy Director


WRS:cm
Enclosure



CALIFORNIA OIL COMPANY

WESTERN DIVISION

1700 BROADWAY • P. O. BOX 780 • DENVER 1 • COLORADO



OIL & GAS
CONSERVATION COMMISSION

February 11, 1964

G. L. KING NO. 2
PIERCE FIELD
Weld County, Colorado

Mr. W. R. Smith
State Services Building
Oil and Gas Conservation Commission
Denver, Colorado

Dear Mr. Smith:

In response to your telephone request, we asked our Casper Division office to send us copies of the work tickets covering the third party well work involved in converting King No. 2 well from a shut-in uneconomic producer in the Lyons formation to a water disposal well. As the work was done over five years ago, the work tickets have been destroyed. However, if you wish, this letter will serve as our authority for you to obtain copies of the work tickets from the service companies involved on the job.

Attached are the copies of the blue pages of tour reports covering the job. The following summarizes the recompletion in question:

When King No. 2 was completed in the Lyons, it produced from the perforated intervals 9250-9260 feet and 9276-9290 feet. The attached Report of Recompletion for water disposal and the tour reports on the subject well indicated the following:

1. Lyons abandoned by setting a cast iron bridge plug at 9240' and spotted 15' of cement on top of the plug.
2. Perforated the Entrada 8558-8578 feet and the Lakota 8230-8265 feet for water disposal.

We have not performed any additional well work on this well since it was recompleted November 10, 1959.



Mr. W. R. Smith
Oil and Gas Conservation Commission
February 11, 1964
Page Two

I have nothing to add except to say that we feel that the conversion procedure was adequate and that it was successful in permitting us to inject Lyons produced water exclusively into the Entrada and Lakota formations.

Sincerely,

E M Dunlap

END:kes

Attachment

DVR	
WRS	
HHM	
JAM	
FJP	
JJD	
FILE	