

Location

Overall Good:

Signs/Marker:

Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment: [Emergency contact number on battery sign requires replacement, see attached photo.](#)

Corrective Action: [Install sign to comply with Rule 605.e.](#)

Date: 02/13/2023

Overall Good:

Spills:

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:

Type	#	Comment	Corrective Action	Date	corrective date
Horizontal Heated Separator	# 2				
Ancillary equipment	# 3	Automation array and two ECD scrubbers			
Pig Station	# 1				
Emission Control Device	# 2	Pilots are on			
Gas Meter Run	# 1	Calibration card is current.			
Bird Protectors	# 4				

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
----------	---	----------	------	---------	--------

PRODUCED WATER	1	100 BBLs	FIBERGLASS AST		
----------------	---	----------	----------------	--	--

Comment:	Anchored				
Corrective Action:					Date:

Paint

Condition	Adequate				
Other (Content)					
Other (Capacity)					
Other (Type)					

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:					
Corrective Action:					Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	2	300 BBLs	STEEL AST		

Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate				
Other (Content)					
Other (Capacity)					
Other (Type)					

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:					
Corrective Action:					Date:

Venting:

Yes/No	NO			
Comment:				
Corrective Action:				Date:

Flaring:

Type				
Comment:				
Corrective Action:				Date:

Inspected Facilities

Facility ID: 481664 Type: TANK API Number: - Status: AC Insp. Status: AC

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary On Thursday 1/12/2023 at approximately 10:40 hours, I, Inspector Tom Peterson, conducted an on-site inspection at the PDC Energy HSR-Elliot Tank Battery location #481664 in Weld County, Colorado. While there, I observed that the emergency contact number decal on the tank battery sign required replacement. During this inspection the following possible compliance issues were observed: Rule 605.e. with a corrective action date of 2/13/2023. A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of the inspection report.</p>	petersont	01/12/2023

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
697007027	Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5981040