



00197805

On July 22, 1986 an inspection was made of the pits constructed as per plane 1. Pit 3 was not constructed but pit 2 is in excellent condition w/ synthetic liner. Location has been cleaned up. Agreed to allow production w/o construction of 3rd pit with monitoring. If well goes on full production, 3rd pit needs to be constructed.