



COLORADO OIL & GAS CONSERVATION COMMISSION
FIELD INSPECTION REPORT



<input checked="" type="checkbox"/> NOTICE OF UNSATISFACTORY INSPECTION		1120 Lincoln Street, Suite 801 Denver, CO 80203 (303)894-2100	
<input type="checkbox"/> NOTICE OF SATISFACTORY INSPECTION			
API No. 05- 107 - 5091		LEASE NAME: Bradley #2	
LOCATION: NENW, 18, 6N, 86W		OPERATOR: B.G. Cannon	
DATE: 8/22/96		INSPECTOR: ADKINS	
Insp. Type: ID	Insp. Status: SI	PA: Y (N)	Pass/Fail: P (F) Viol.: (Y) N NOV: (Y) (N)

INSPECTION ITEM	COMMENTS	INPUT
Well ID Signs (Rule 210, 604.c(4))	ok	
Pits (Reserve/Production) (Rule 902, 903, 904, 905)	none, well in river bottom	✓
Fences (Rule 603.b.7, 604.C.(3), 1002.A)	none	
Tank Battery Equipment (Rule 603.b.3, 604)	1-small RPU on 8' Substructure (in floodplain) Flowline disconnected	✓
Fire Walls/Berms/Dikes (Rule 603.b.12, 604)	none	
General Housekeeping (Rule 603)	ok	
Spills (Oil/Water) (Rule 907)	oil stained soil around wellhead	
Bradenhead (Rule 207.b)	surface sig sticks up 8' or so.	
Drilling Well/Workover (Rule 317)	n/a	
Surface Rehabilitation (Rule 1002, 1003, 1004, 1103)	ok	
Miscellaneous 319.b.(3) 326.b.(1)	well has been SI for an extended period.	

CORRECTIVE ACTION REQUIRED: Perform MIT or PTA by 8-1-97	
Date Corrective Action Required By: 8-1-97	Date Remedied:

This report is a Notice of Inspection. The Commission requires that you correct any deficiencies shown on this report in a timely manner. Failure to comply may result in enforcement action by the Commission.