

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
403279392

Date Received:
01/11/2023

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

5 of 5 CAs from the FIR responded to on this Form

5 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10433

Name of Operator: LARAMIE ENERGY LLC

Address: 1700 LINCOLN ST STE 3950

City: DENVER State: CO Zip: 80203

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name	Phone	Email
<u>Laramie</u>		<u>cogccnotifications@laramie-energy.com</u>
<u>Arauzo, Steven</u>		<u>steven.arauza@state.co.us</u>

COGCC INSPECTION SUMMARY:

FIR Document Number: 696204555

Inspection Date: 12/27/2022

FIR Submit Date: 12/30/2022

FIR Status: _____

Inspected Operator Information:

Company Name: LARAMIE ENERGY LLC

Company Number: 10433

Address: 1700 LINCOLN ST STE 3950

City: DENVER State: CO Zip: 80203

LOCATION - Location ID: 452807

Location Name: CC Number: 0697-03-07 County: _____
Pad

Qtrqtr: Lot 11 Sec: 3 Twp: 6S Range: 97W Meridian: 6

Latitude: 39.558439 Longitude: -108.205081

FACILITY - API Number: 05-045-00 Facility ID: 452807

Facility Name: CC Number: 0697-03-07
Pad

Qtrqtr: Lot 11 Sec: 3 Twp: 6S Range: 97W Meridian: 6

Latitude: 39.558439 Longitude: -108.205081

CORRECTIVE ACTIONS:

1 CA# 166843

Corrective Action: Securely fasten all valves, pipes, fittings, and Production Facilities to ensure good mechanical condition. Control and contain spills/releases and clean up per Rule 912.a. Report spill if spill ir a reportable volume.

Date: 12/28/2022

Response: CA COMPLETED

Date of Completion: 01/03/2023

Drips on camlock connections have been stopped. Either the 4" gasket was replaced or the locking ears were shimmed. We will pay close attention to make sure no other leaks develop. All containments have been dug out

Operator Comment: and cleared of ice and snow and the brackets installed to hold up the sides of the containments. All snow and ice removed from containments was thrown into the frac tanks we are pumping out of.

COGCC Decision: Approved pending re-inspection

COGCC Representative: Approved pending re-inspection. Based on photo documentation provided, work to address the corrective action appears to have been performed. A field inspection will be conducted at a future date to evaluate compliance with COGCC rules.

2 CA# 166844

Corrective Action: Install wildlife protection devices. Date: 01/30/2023

Response: CA COMPLETED Date of Completion: 01/10/2023

Operator Comment: Combustor bird/rodent barrier has been installed

COGCC Decision: Approved pending re-inspection

COGCC Representative: Approved pending re-inspection. Based on photo documentation provided, work to address the corrective action appears to have been performed. A field inspection will be conducted at a future date to evaluate compliance with COGCC rules.

3 CA# 166845

Corrective Action: Install label information on containers on Location to allow for content identification. Date: 01/30/2022

Response: CA COMPLETED Date of Completion: 01/03/2023

Operator Comment: Containers were removed from location.

COGCC Decision: Approved pending re-inspection

COGCC Representative: Approved pending re-inspection. Based on photo documentation provided, work to address the corrective action appears to have been performed. A field inspection will be conducted at a future date to evaluate compliance with COGCC rules.

4 CA# 166846

Corrective Action: Comply with Rule 606. Date: 01/06/2023

Response: CA COMPLETED Date of Completion: 01/03/2023

Operator Comment: Unused tarps and liners have been removed from location. All containment's have been dug out and cleared of ice and snow and the brackets installed to hold up the sides of the containments. All snow and ice removed from containment's was thrown into the frac tanks we are pumping out of.

COGCC Decision: Approved pending re-inspection

COGCC Representative: Approved pending re-inspection. Based on photo documentation provided, work to address the corrective action appears to have been performed. A field inspection will be conducted at a future date to evaluate compliance with COGCC rules.

5 CA# 166847

Corrective Action: Comply with 1002.f. Date: 01/03/2023

Response: CA COMPLETED Date of Completion: 01/05/2023

Operator Comment: red pumps have been removed from location and area around them have been cleaned up.Drips on camlock connections have been stopped. Either the 4" gasket was replaced or the locking ears were shimmed.

COGCC Decision: Approved pending re-inspection

COGCC Representative: Approved pending re-inspection. Based on photo documentation provided, work to address the corrective action appears to have been performed. A field inspection will be conducted at a future date to evaluate compliance with COGCC rules.

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Lori Muhr

Signed: _____

Title: Regulatory Specialist

Date: 1/11/2023 6:39:02 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
403279392	FIR RESOLUTION SUBMITTED
403285865	Corrective Action Photos

Total Attach: 2 Files