

Location

Overall Good:

Signs/Marker:

Type	WELLHEAD		
Comment:	adequate		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action: Date: _____

Overall Good:

Spills:

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

Type	OTHER		
Comment:	ancillary equip has fabricated steel pipe and round stock		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	barb wire/hog fence		
Corrective Action:		Date:	
Type	PUMP JACK		
Comment:	fabricated angle iron		
Corrective Action:		Date:	

Equipment:

Type			corrective date
Type: Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	
Type: Prime Mover	# 1		
Comment:	electric motor		
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	electric panel, meter box and transformers		
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:	appears plumbed to surface		
Corrective Action:		Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 241111 Type: WELL API Number: 123-08899 Status: PR Insp. Status: PR

Producing Well

Comment: PR

Corrective Action:

Date:

BradenHead

Date of Last Brhd Test: 08/25/2022 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 6 Fluid Type: _____

End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary On Wednesday 1-25-2023 at approximately 1440 hrs. I, Inspector Robbie Revas, Conducted an on-site inspection: Operator: KP Kauffman Location name: Dutcher C2 API #05-123-08899 County: Weld Weather: Cloudy/cold. Location: Snow covered While there, I observed wellsite, PR at the time of inspection. During this inspection, I observed no compliance issues: See attached photos. No follow up site inspection is needed to ensure that the addressed Compliance issues comply with COGCC rules.</p>	revasr	01/25/2023

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
702401467	location pics	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5996978