

State of Colorado  
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:  
403156214

Date Received:  
09/07/2022

## FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

1 of 1 CAs from the FIR responded to on this Form

1 CA Completed  
0 Factual Review Request

### OPERATOR INFORMATION

OGCC Operator Number: 10669

Name of Operator: NICKEL ROAD OPERATING LLC

Address: 44 COOK ST STE 705

City: DENVER State: CO Zip: 80206

Contact Name and Telephone:

Name: \_\_\_\_\_

Phone: ( ) \_\_\_\_\_ Fax: ( ) \_\_\_\_\_

Email: \_\_\_\_\_

Additional Operator Contact:

Contact Name

Phone

Email

Erin Lind

3032267375

erin.lind@nickelroadoperating.com

### COGCC INSPECTION SUMMARY:

FIR Document Number: 679605056

Inspection Date: 08/31/2022

FIR Submit Date: 08/31/2022

FIR Status: \_\_\_\_\_

### Inspected Operator Information:

Company Name: NICKEL ROAD OPERATING LLC

Company Number: 10669

Address: 44 COOK ST STE 705

City: DENVER State: CO Zip: 80206

### LOCATION - Location ID: 478497

Location Name: BLEHM PAD Number: \_\_\_\_\_ County: \_\_\_\_\_

Qtrqr: NENE Sec: 9 Twp: 7N Range: 67W Meridian: 6

Latitude: 40.595004 Longitude: -104.890847

### FACILITY - API Number: 05-123-00 Facility ID: 478497

Facility Name: BLEHM PAD Number: \_\_\_\_\_

Qtrqr: NENE Sec: 9 Twp: 7N Range: 67W Meridian: 6

Latitude: 40.595004 Longitude: -104.890847

### CORRECTIVE ACTIONS:

1 ☒ CA# 164305

Corrective Action: Conduct maintenance on equipment, cleanup stained material and review self inspection processes per Rule 1002.(2).d.

Date: 09/30/2022

Response: CA COMPLETED

Date of Completion: 09/06/2022

Operator Comment: Upon notification of inspection report on 9/2/22, Nickel Road immediately began cleanup of the stained material around the cellars of all ten wellheads. The material was dug up, cellars were power washed and all were replaced with fresh pea gravel. Inspections were done on all ten wellhead connections and pressure tested. Nickel Road verified there were no leaks.

COGCC Decision: Approved pending re-inspection

COGCC  
Representative:

**OPERATOR COMMENT AND SUBMITTAL**

Comment: FIRR submitted in response to Doc #679605056. See response on "Corrective Actions & Responses" tab.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: ERIN LIND

Signed: \_\_\_\_\_

Title: SR REG ANALYST

Date: 9/7/2022 12:25:07 PM

**ATTACHMENT LIST**

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<b><u>Document Number</u></b>	<b><u>Description</u></b>
-------------------------------	---------------------------

403156214	FIR RESOLUTION SUBMITTED
-----------	--------------------------

Total Attach: 1 Files