



COLORADO OIL & GAS CONSERVATION COMMISSION
FIELD INSPECTION REPORT

2

<input checked="" type="checkbox"/> NOTICE OF UNSATISFACTORY INSPECTION		1120 Lincoln Street, Suite 801 Denver, CO 80203 (303)894-2100	
<input type="checkbox"/> NOTICE OF SATISFACTORY INSPECTION			
API No. 05- 061 - 6104		LEASE NAME: DAWSON #5	
LOCATION: NENE 8-19S-46W ^{75W}		OPERATOR: WESTERN DP	
DATE: 11-12-98		INSPECTOR: R. Vamsickel	
Insp. Type: SR	Insp. Status: PA	PA: Y <input type="radio"/> N <input checked="" type="radio"/>	Pass/Fail: P <input type="radio"/> F <input checked="" type="radio"/> Viol.: Y <input checked="" type="radio"/> N <input type="radio"/> NOV: Y <input type="radio"/> N <input checked="" type="radio"/>

INSPECTION ITEM	COMMENTS	INPUT
Well ID Signs (Rule 210, 604.c(4))		
Pits (Reserve/Production) (Rule 902, 903, 904, 905)		
Fences (Rule 603.b.7, 604.C.(3), 1002.A)		
Tank Battery Equipment (Rule 603.b.3, 604)		
Fire Walls/Berms/Dikes (Rule 603.b.12, 604)		
General Housekeeping (Rule 603)		
Spills (Oil/Water) (Rule 907)		
Bradenhead (Rule 207.b)		
Drilling Well/Workover (Rule 317)		
Surface Rehabilitation (Rule 1002, 1003, 1004, 1103)	4 WS anchors need removal.	✓
Miscellaneous		

JAN 19 1999

CORRECTIVE ACTION REQUIRED: Pull anchors & markers markers	
Date Corrective Action Required By: 1-15-99	Date Remedied:

This report is a Notice of Inspection. The Commission requires that you correct any deficiencies shown on this report in a timely manner. Failure to comply may result in enforcement action by the Commission.