

FORM
INSPRev
X/20State of Colorado
Oil and Gas Conservation Commission1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

02/07/2023

Submitted Date:

02/10/2023

Document Number:

702801241

FIELD INSPECTION FORM

 Loc ID 311583 Inspector Name: O'Malley, Anna On-Site Inspection 2A Doc Num: _____
Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:
 OGCC Operator Number: 96850
 Name of Operator: TEP ROCKY MOUNTAIN LLC
 Address: 1058 COUNTY ROAD 215
 City: PARACHUTE State: CO Zip: 81635
Findings:
 3 Number of Comments
 0 Number of Corrective Actions
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
 PREVIOUS INSPECTIONS THAT HAVE NOT
 BEEN ADDRESSED ARE STILL APPLICABLE**
Contact Information:

Contact Name	Phone	Email	Comment
, TEP		COGCCInspectionReports@terraep.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
311583	LOCATION	AC			-	CLOUGH-66S94W 28NWNW	RI

General Comment:

On 2/7/2023, Reclamation Specialist O'Malley conducted a field inspection at TEP Rocky Mountain LLC's CLOUGH-66S94W/28NWNW Location #311583 in Garfield County, Colorado.

This is a follow up to inspection #702801111 to assess compliance with a stormwater corrective action; the corrective action has been addressed.

Refer to the "Stormwater" section of this inspection report for additional details.

Refer to the photo-documentation attached to this report.

Any corrective action(s) from previous inspections that have not been addressed are still applicable.

Inspected Facilities

Facility ID: 311583 Type: LOCATION API Number: - Status: AC Insp. Status: RI

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: It was observed in this inspection that gravel has been recently installed on the pad to address stabilization and tracking issues. Corrective action from inspection #702801111 has been addressed. The location remains partially snow covered. Unable to perform full stormwater inspection.

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
702801242	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6017138