

FORM
INSPRev
X/20State of Colorado
Oil and Gas Conservation Commission1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

02/10/2023

Submitted Date:

02/13/2023

Document Number:

696204634

FIELD INSPECTION FORM

 Loc ID 314788 Inspector Name: Trujillo, Aaron On-Site Inspection 2A Doc Num: _____
Operator Information:OGCC Operator Number: 16700Name of Operator: CHEVRON USA INCAddress: 760 HORIZON DRIVE STE 401City: GRAND JUNCTION State: CO Zip: 81506**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Findings:10 Number of Comments0 Number of Corrective Actions Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
,		RangelyRegulatory@scoutep.com	Rangely Field
		andrewolson@chevron.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
229585	WELL	PR	08/01/2015	OW	103-07242	F V LARSON B-23X	RI
314788	LOCATION	AC			-	F V LARSON-62N102W 35NESW	RI

General Comment:

On 2/10/2023, Reclamation Specialist Trujillo inspected Chevrans USA's F V Larson B-23X Location in Rio Blanco County, Colorado.

Form 9(s) 402890528 transferring Location from Chevron USA to Scout Energy Management #10779 currently "in process"; Chevron remains the Operator on record for the Location until Form 9 is approved.

Limited visibility inspection due to snow cover- no issues observed at time of inspection.

Refer to the "Location", "Reclamation" and "stormwater" sections of this inspection report for additional details.

Any corrective action(s) from previous inspections that have not been addressed are still applicable.

Location

Overall Good:

Signs/Marker:

Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:	970-675-3700 / 911		
Corrective Action:		Date:	

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

Type	WELLHEAD		
Comment:	Chain link fence		
Corrective Action:		Date:	

Equipment:

				corrective date
Type:	Horizontal Heated Separator	#		
Comment:	Off-Location flowline system- Facility ID 479404			
Corrective Action:		Date:		

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 229585 Type: WELL API Number: 103-07242 Status: PR Insp. Status: RI

Facility ID: 314788 Type: LOCATION API Number: - Status: AC Insp. Status: RI

Reclamation - Storm Water - Pit

Interim Reclamation:

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: _____

Comment: _____

1002 SITE PREPARATION AND STABILIZATION

1002a. FENCING _____

Comment _____

Corrective Action _____

Date _____

1002b. SOIL REMOVAL AND _____

Comment _____

Corrective Action _____

Date _____

1002c. PROTECTION OF SOILS _____

Comment _____

Corrective Action _____

Date _____

1002E. SURFACE DISTURBANCE MINIMIZATION _____

Comment _____

Corrective Action _____

Date _____

1003a. Waste and Debris removed? Pass

Comment No waste or debris observed on the production and interim areas of the Location.

Corrective Action _____

Date _____

Unused or unneeded equipment onsite? Pass

Comment No unused or unneeded equipment observed on the production and interim areas of the Location.

Corrective Action _____

Date _____

Pit, cellars, rat holes and other bores closed? _____

Comment _____

Corrective Action _____

Date _____

Guy line anchors marked? _____

Comment Limited visibility inspection due to winter conditions and snow cover; unable to observe anchors, though markers were observed.

Corrective Action _____

Date _____

1003b. Area no longer in use? _____ Production areas stabilized ? _____
 1003c. Compacted areas have been cross ripped? _____
 1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____
 Cuttings management: _____
 1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____
 Production areas have been stabilized? _____ Segregated soils have been replaced? _____

RESTORATION AND REVEGETATION

Cropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced _____ Recontoured _____ 80% Revegetation _____

1003e. INTERIM VEGETATION TRANSECT
 TRANSECT RESULTS OF DISTURBED AREA% _____
 TRANSECT RESULTS OF REFERENCE AREA% _____
 TOTAL % OF DESIRABLE VEGETATION COVER _____
 VEGETATIVE COVER _____

1003 f. Weeds Noxious weeds? _____

Comment Limited visibility Reclamation inspection due to winter conditions; no immediate reclamation concerns identified. Noxious weeds not apparent at time of inspection, A followup inspection will be conducted in the future growing season to determine compliance with 1003 rules.

Corrective Action Date _____

Overall Interim Reclamation

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: _____

Reminder: _____

Comment:

Well plugged _____ Pit mouse/rat holes, cellars backfilled _____

Debris removed _____ No disturbance /Location never built _____

Access Roads Regraded _____ Contoured _____ Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____ Locations, facilities, roads, recontoured _____

Compaction alleviation _____ Dust and erosion control _____

Non cropland: Revegetated 80% _____ Cropland: perennial forage _____

Weeds present _____ Subsidence _____

1004.d. FINAL VEGETATION TRANSECT
 TRANSECT RESULTS OF DISTURBED AREA% _____
 TRANSECT RESULTS OF REFERENCE AREA% _____
 TOTAL % OF DESIRABLE VEGETATION COVER _____
 VEGETATIVE COVER _____

Comment:

Corrective Action: Date _____

Overall Final Reclamation	Well Release on Active Location <input type="checkbox"/>	Multi-Well Location <input type="checkbox"/>
---------------------------	--	--

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: Limited visibility stormwater inspection due to winter conditions and snow cover; no immediate stormwater issues observed at time of inspection.

Corrective Action: Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
696204635	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6018795