

FORM
6Rev
02/20

State of Colorado

Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303) 894-2100 Fax: (303) 894-2109



DE	ET	OE	ES
----	----	----	----

Document Number:

402457222

Date Received:

08/20/2020

WELL ABANDONMENT REPORT

This form is to be submitted as an Intent to Abandon whenever an abandonment is planned on a borehole. After the abandonment is complete, this form shall again be submitted as a Subsequent Report of the actual work completed. The approved intent shall be valid for six months after the approval date, after that period, a new intent will be required. Attachments required with the Intent to Abandon are wellbore diagrams of the current configuration and the proposed configuration with plugs set.

A Subsequent Report of Abandonment shall indicate the actual work completed. Attachments required with a Subsequent Report are a wellbore diagram showing plugs that were set and casing remaining in the hole, the job summaries from all plugging contractors used, including wireline and cementing (third party verification) and any logs that may have been run during abandonment.

OGCC Operator Number: 72400

Contact Name: Jeff Schneider

Name of Operator: PUBLIC SERVICE COMPANY OF COLORADO

Phone: (970) 867-9437

Address: 112 W 3RD AVE

Fax: (970) 867-9137

City: DENVER State: CO Zip: 80223

Email: jeff@schneiderenergy.com

For "Intent" 24 hour notice required,

Name: Schure, Kym

Tel: (303) 894-2100

COGCC contact:

Email: kym.schure@state.co.us

Type of Well Abandonment Report: ☐ Notice of Intent to Abandon ☒ Subsequent Report of Abandonment

API Number 05-087-08006-00

Well Name: STORAGE UNIT

Well Number: 33

Location: QtrQtr: CNE Section: 34 Township: 2N Range: 60W Meridian: 6

County: MORGAN

Federal, Indian or State Lease Number:

Field Name: ROUNDUP

Field Number: 74950

Only Complete the Following Background Information for Intent to Abandon

Latitude: 40.100720 Longitude: -104.079820

GPS Data: GPS Quality Value: 1.4 Type of GPS Quality Value: PDOP Date of Measurement: 06/30/2010

GPS Instrument Operator's Name: Paul Kellog

Reason for Abandonment: ☐ Dry ☐ Production Sub-economic ☐ Mechanical Problems☐ OtherCasing to be pulled: ☐ Yes ☐ No Estimated Depth:Fish in Hole: ☐ Yes ☐ No If yes, explain details belowWellbore has Uncemented Casing leaks: ☐ Yes ☐ No If yes, explain details below

Details:

Current and Previously Abandoned Zones

Formation	Perf. Top	Perf. Btm	Abandoned Date	Method of Isolation	Plug Depth
J SAND	6420	6428	07/31/2020	B PLUG CEMENT TOP	6370

Total: 1 zone(s)

Casing History

Casing Type	Size of Hole	Size of Casing	Weight Per Foot	Setting Depth	Sacks Cement	Cement Bot	Cement Top	Status
SURF	12+1/4	8+5/8	24	317	285	317	0	VISU
1ST	7+7/8	5+1/2	15.5	6,550	400	6,550	4,760	CBL

Plugging Procedure for Intent and Subsequent Report

CIBP #1: Depth 6370 with 4 sacks cmt on top. CIBP #2: Depth 5460 with 4 sacks cmt on top.
CIBP #3: Depth _____ with _____ sacks cmt on top. CIBP #4: Depth _____ with _____ sacks cmt on top.
CIBP #5: Depth _____ with _____ sacks cmt on top.

NOTE: Two(2) sacks cement required on all CIBPs.

Set 5 sks cmt from 2452 ft. to 2400 ft. Plug Type: CASING Plug Tagged: ☐
Set 40 sks cmt from 367 ft. to 30 ft. Plug Type: CASING Plug Tagged: ☒
Set _____ sks cmt from _____ ft. to _____ ft. Plug Type: _____ Plug Tagged: ☐
Set _____ sks cmt from _____ ft. to _____ ft. Plug Type: _____ Plug Tagged: ☐
Set _____ sks cmt from _____ ft. to _____ ft. Plug Type: _____ Plug Tagged: ☐

Perforate and squeeze at 2500 ft. with 55 sacks. Leave at least 100 ft. in casing 2452 CICR Depth

Perforate and squeeze at 367 ft. with 60 sacks. Leave at least 100 ft. in casing _____ CICR Depth

Perforate and squeeze at _____ ft. with _____ sacks. Leave at least 100 ft. in casing _____ CICR Depth

(Cast Iron Cement Retainer Depth)

Set _____ sacks half in. half out surface casing from _____ ft. to _____ ft. Plug Tagged: ☐

Set 4 sacks at surface

Cut four feet below ground level, weld on plate Above Ground Dry-Hole Marker: ☐ Yes ☒ No

Set _____ sacks in rat hole Set _____ sacks in mouse hole

Additional Plugging Information for Subsequent Report Only

Casing Recovered: _____ ft. _____ inch casing Cut and Cap Date: 08/05/2020

*Wireline Contractor: Pioneer Energy Services

*Cementing Contractor: Yetter Well Service

Type of Cement and Additives Used: Type 2

Flowline/Pipeline has been abandoned per Rule 1105 ☐ Yes ☐ No

Technical Detail/Comments:

I hereby certify all statements made in this form are, to the best of my knowledge, true, correct, and complete.

Signed: _____ Print Name: Jeff Schneider

Title: Consultant Date: 8/20/2020 Email: jeff@schneiderenergy.com

Based on the information provided herein, this Well Abandonment Report (Form 6) complies with COGCC Rules and applicable orders and is hereby approved.

COGCC Approved: Wolfe, Stephen Date: 2/13/2023

CONDITIONS OF APPROVAL, IF ANY:

COA Type Description

0 COA	

Attachment List

<u>Att Doc Num</u>	<u>Name</u>
402457222	FORM 6 SUBSEQUENT SUBMITTED
402472198	WIRELINE JOB SUMMARY
402472205	CEMENT JOB SUMMARY
402472219	OTHER
402472251	WELLBORE DIAGRAM

Total Attach: 5 Files

General Comments

<u>User Group</u>	<u>Comment</u>	<u>Comment Date</u>
		Stamp Upon Approval

Total: 0 comment(s)