

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
403320432

Date Received:
02/14/2023

FIR RESOLUTION FORM

Overall Status:

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 96850

Name of Operator: TEP ROCKY MOUNTAIN LLC

Address: 1058 COUNTY ROAD 215

City: PARACHUTE State: CO Zip: 81635

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

TEP

COGCCInspectionReports@terraep.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 696204628

Inspection Date: 02/03/2023

FIR Submit Date: 02/06/2023

FIR Status: _____

Inspected Operator Information:

Company Name: TEP ROCKY MOUNTAIN LLC

Company Number: 96850

Address: 1058 COUNTY ROAD 215

City: PARACHUTE State: CO Zip: 81635

LOCATION - Location ID: 159652

Location Name: YATER PAD Number: _____ County: _____

Qtrqr: NWS Sec: 17 Twp: 7S Range: 95W Meridian: 6
W

Latitude: 39.435195 Longitude: -108.026397

FACILITY - API Number: 05-045- -00 Facility ID: 159652

Facility Name: YATER PAD Number: _____

Qtrqr: NWS Sec: 17 Twp: 7S Range: 95W Meridian: 6
W

Latitude: 39.435195 Longitude: -108.026397

CORRECTIVE ACTIONS:

1 CA# 167287

Corrective Action: Comply with Rule 606.

Date: 02/13/2023

Response: CA COMPLETED

Date of Completion: 02/13/2023

Operator Comment: Straw bales and paneling have been removed. Corrective action complete.

COGCC Decision: _____

COGCC Representative:			
2	CA# 167288		
Corrective Action:	Comply with Rule 606.		Date: <u>02/13/2023</u>
Response:	CA COMPLETED		Date of Completion: <u>02/13/2023</u>
Operator Comment:	Weed debris has been removed from areas noted in inspection. Note: Many of the weeds removed were Russian Thistle (tumbleweeds) that have blown on site from surrounding areas. TEP Production personnel have also made arrangements to have spray this area in the spring to prevent weed growth from beginning. Off-site weeds blowing onto location will still be an issue. TEP also has a brush-hog that will be used to keep portions of the pad mowed and the amount of weeds growing on the pad minimized. Corrective Action complete.		
COGCC Decision:			
COGCC Representative:			

OPERATOR COMMENT AND SUBMITTAL	
Comment:	Corrective actions #167287 and #168288 have been completed.
I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.	
Print Name: <u>Michael Gardner</u>	Signed: _____
Title: <u>TEP Environmental Lead</u>	Date: <u>2/14/2023 11:58:25 AM</u>

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>

Total Attach: 0 Files