



Horton 33-6





Conducted Maintenance on equipment, cleaned up stained material and reviewed self-inspection to comply with Rule 1002,. (2)D. (Repaired Leaking Equipment)



Complied with Rule 1002.f.(2)B, Complied with general provisions of the oil and gas act for wildlife protection and SB-181.





Installed appropriate fittings to allow bradenhead visual inspection as per Rule 419.a.(1), (2)