

15-195-45W

INEXCO  
OIL COMPANY

RECEIVED

FEB 20 1985



February 15, 1985

Bureau of Land Management  
3080 E. Main Street  
Canon City, Colorado 81212

RE: Federal Lease #C-0123458-A  
USA Butler #1, #1X, & #2  
USA 1-15, 2-15  
Brandon Field  
Kiowa County, Colorado

Attention: Frank Moore

Dear Mr. Moore,

Attached is the following information which was requested by Mr. Bob Egan of your office.

- Butler #1 Sundry notice for recompletion in the Lansing L-13.
- Butler #2 Well sign has been corrected to reflect that lease has fee ownership of both minerals and land.
- Butler Lease Approval June 6, 1972 by State of Colorado for application of earthen pit. The copy in BLM files dated August 21, 1974, by J. C. Simmons was to notify the State of an upgrade on the pit; the pit was lined with a neoprene liner.
- USA #2-15 Sundry notices for Change of Operator and Temporary Abandoned status of well. We are re-evaluating the well logs to determine if any productive zones are present. Also, for your files is a copy of the completion report. We do not have any production information on the well; you will have to contact Tenneco to get that information. Our estimates indicate it produced less than 3,000 barrels of oil and less than 20,000 barrels of water.
- Butler Lease Hydrogen Sulfide Contingency Plan - We have contracted Oilind Safety to put together a H2S contingency plan and will forward it to your attention as soon as its completed.

RECEIVED


FEB 20 1985

COLORADO OIL & GAS CONS. COMM.

Previous testing has shown very low concentrations of H<sub>2</sub>S.

Please let us know if any additional information is needed.

Sincerely,

  
W. R. Emmett  
Division Operations Manager

TJC/lrb  
Attachments

cc: Ken Gideons  
Well Files  
State of Colorado

WIS	
FJP	
HND	
JAN	
POE	
LAT	
COM	
ED	