

State of Colorado  
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

403325490

Date Received:

02/21/2023

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

1 of 1 CAs from the FIR responded to on this Form

1 CA Completed  
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 16700

Name of Operator: CHEVRON USA INC

Address: 760 HORIZON DRIVE STE 401

City: GRAND JUNCTION State: CO Zip: 81506

Contact Name and Telephone:

Name: \_\_\_\_\_

Phone: ( ) \_\_\_\_\_ Fax: ( ) \_\_\_\_\_

Email: \_\_\_\_\_

Additional Operator Contact:

Contact Name

Phone

Email

Sanford, Anita RangelyRegulatory@scoutep.com

Olson, Andrew Anita.Sanford@scoutep.com

AndrewOlson@chevron.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 696204641

Inspection Date: 02/10/2023

FIR Submit Date: 02/13/2023

FIR Status: \_\_\_\_\_

Inspected Operator Information:

Company Name: CHEVRON USA INC

Company Number: 16700

Address: 760 HORIZON DRIVE STE 401

City: GRAND JUNCTION State: CO Zip: 81506

LOCATION - Location ID: 314601

Location Name: LEVISON-62N102W Number: 26SWSE County: \_\_\_\_\_

Qtrqr: SWSE Sec: 26 Twp: 2N Range: 102W Meridian: 6

Latitude: 40.108490 Longitude: -108.808090

FACILITY - API Number: 05-103- -00 Facility ID: 314601

Facility Name: LEVISON-62N102W Number: 26SWSE

Qtrqr: SWSE Sec: 26 Twp: 2N Range: 102W Meridian: 6

Latitude: 40.108490 Longitude: -108.808090

CORRECTIVE ACTIONS:

1 ☒ CA# 167618

Corrective Action: Ensure production facilities, valves, pipes, fittings, and vessels are securely fastened or sealed, and maintained in good mechanical condition. Any Stowmater (Snow, snowmelt, ice, etc...) in contact with potential E&P Waste is required to be removed.

Date: 02/20/2023

Response: CA COMPLETED

Date of Completion: 02/20/2023

Please see attached. Drip from valve was excessive grease from valve packing. No leaks were found. Waste

Operator Comment: was disposed of properly and snow was removed.

COGCC Decision: Approved

COGCC Representative: CA has been resolved.

OPERATOR COMMENT AND SUBMITTAL

Comment: Please se attached. Drip from valve was excessive grease from valve packing. No leaks were found. Waste was disposed of properly and snow was removed.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Chris Patterson

Signed:

Title: Sr. HSE Coordinator

Date: 2/21/2023 7:16:27 AM

**ATTACHMENT LIST**

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

**Document Number**      **Description**

403325490	FIR RESOLUTION SUBMITTED
403325491	Photo

Total Attach: 2 Files