

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

02/23/2023

Submitted Date:

02/23/2023

Document Number:

699106526

FIELD INSPECTION FORMLoc ID _____ Inspector Name: Burns, Adam On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 46290

Name of Operator: KP KAUFFMAN COMPANY INC

Address: 1700 LINCOLN ST STE 4550

City: DENVER State: CO Zip: 80203

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

4 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Kraich, Adam		adam.kraich@state.co.us	
Medina, Justin		justin.medina@state.co.us	
Ferrin, Jeremy		jeremy.ferrin@state.co.us	
,		cogcc@kpk.com	All Inspections
Leonard, Mike		mike.leonard@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
478836	Flowline System	AC	12/17/2020		-	Facility 5	AC

General Comment:

LocationOverall Good: ☐

Emergency Contact Number:

Comment: Corrective Action: Date: Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Equipment:**

Type: Gas Meter Run	#		corrective date
Comment:	Appears to have sold product. Couldnt location gas meter run. Pumper indicated it was North of CR. 52 on CR. 19.		
Corrective Action:	Immediately cease all gas sales pursuant to Order 1V-863. Further gas sales from this battery is a violation of Rule 219 and Order 1V-863		Date:

Venting:

Yes/No		
Comment:		
Corrective Action:		Date:

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities			
Facility ID: 478836	Type: Flowline	API Number: -	Status: AC
Insp. Status: AC			
Producing Well			
Comment:	AC		
Corrective Action:		Date:	
COGCC Comments			
Comment	User	Date	
<p>COGCC Inspection Report Summary</p> <p>On Thursday 2/23/23 at approximately 1100hrs, I, Inspector Adam Burns, Conducted an on-site inspection at Facility 5 of KP Kauffman Company inc, at Facility ID: 478836 in Weld County, Colorado.</p> <p>During this inspection the following possible compliance issues were observed:</p> <p>Appears to have sold product. Immediately cease all gas sales pursuant to Order 1V-863.</p> <p>Further gas sales from this battery is a violation of Rule 219 and Order 1V-863</p> <p>Couldn't track down the gas meter run. The pumper on location indicated it was North of CR. 52 on CR. 19.</p> <p>Splinter "A" Trucking inc was on location pulling crude oil and transporting it to whitecliffs pipeline.</p> <p>All balon valves appear to be open on bulk separator.</p> <p>Wells that flow into this facility include the following:</p> <p>123-07566 ROBERT G BURGE 1</p> <p>123-09097 ALEX H MILLER 2</p> <p>123-08976 ALEX H MILLER 1</p> <p>123-09211 ROBERT G BURGE 2</p> <p>123-07528 UPRR 42 PAN AM E 3</p> <p>123-07527 UPRR 42 PAN AM E 2</p> <p>123-08789 UPRR 42 PAN AM E 6</p> <p>123-08868 UPRR 42 PAN AM E 5</p> <p>123-08996 UPRR 42 PAN AM E 4</p> <p>123-07493 DONALD E MILLER ET AL B 1</p> <p>123-08790 VERA L MCCANNON 2</p> <p>123-07465 VERA L MCCANNON 1</p> <p>123-07679 MILLER*DONALD E B-2</p> <p>123-08791 MCCANNON UNIT 2</p> <p>123-08977 DONALD E MILLER B 3</p> <p>123-19989 ROCKY MOUNTAIN FUEL CO 9-8</p> <p>123-07477 ROCKY MOUNTAIN FUEL CO B 1</p> <p>123-07526 ROCKY MOUNTAIN FUEL CO C 2</p> <p>123-07677 ROCKY MOUNTAIN FUEL CO C 4</p> <p>123-08840 ROCKY MOUNTAIN FUEL B 3</p> <p>123-08871 ROCKY MOUNTAIN FUEL CO C 7</p> <p>123-12569 ROCKY MOUNTAIN FUEL C-9</p> <p>123-15949 ROCKY MOUNTAIN FUEL 33-9</p> <p>123-15955 ROCKY MOUNTAIN FUEL 12-9</p> <p>123-19990 ROCKY MOUNTAIN FUEL CO 15-9</p> <p>123-07479 ROCKY MOUNTAIN FUEL CO C 1</p> <p>123-09983 ROCKY MOUNTAIN FUEL CO C 8</p> <p>123-12745 ROCKY MOUNTAIN FUEL C-10</p> <p>123-08874 SUCKLA-BROWN UNIT 13</p> <p>123-07480 SUCKLA-BROWN UNIT 1</p> <p>123-07484 SUCKLA-BROWN UNIT 8</p> <p>123-07485 SUCKLA-BROWN UNIT NAV 7</p> <p>123-08873 SUCKLA-BROWN UNIT 12</p> <p>123-08877 SUCKLA-BROWN UNIT 16</p> <p>123-09485 SUCKLA-BROWN UNIT 17</p> <p>123-07578 DORIS ACKERSON UNIT 1</p> <p>123-07511 UPRR 42 PAN AM F 1</p> <p>123-07572 UPRR 42 PAN AM F 3</p>	burnsa	02/23/2023	

Inspector Name: Burns, Adam

123-08699 DORIS ACKERSON UNIT	2
123-08878 UPRR 42 PAN AM F	5
123-08892 UPRR 42 PAN AM F	4
123-09563 DORIS ACKERSON UNIT	4
123-09083 UPRR 42 PAN AM AG	2
123-08692 UPRR 42 PAN AM AG	1
123-13578 UPRR 42 PAN AM AG	3

They all feed into one Bulk Separator on location.

See attached photos.

A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.

This is a summary of inspection report.

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699106527	Inspection Photo	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6031697