



COLORADO OIL AND GAS CONSERVATION COMMISSION - UIC FIELD REPORT

FAC# 155 API# 061 06045 0 INSPECTOR L. Robbins DATE 7/7/87WELL NAME NW BRANDON UNIT 5-1 TYPE E SITE INSPECTION X

FIELD 7500 BRANDON WITNESS MIT _____

OPER 43100 INEXCO OIL CO

LOCATION NESE 5 19.0S 45.0W 6

MAX PERMITTED PRESS 1263 PSI DATE LAST INSPECTION 07/15/86 OUTCOME A
LAST REPORTED PRESS PSI 00/00 DATE LAST MIT 00/00/00
WELL RESTRICTIONS OPEN PERFS 3700-3705? SHUT-IN SINCE 7/78
REMEDIAL ACTION
COMPLETION TYPE TP

TUBING PRESSURE

ZONE STLSP

MIT _____ INJECTING _____ PSI

MIT _____ NOT INJECTING SI PSI

TUBING-CASING ANNULUS _____ PSI

BRAIDENHEAD _____ PSI

TOP 4555
BOT 4730

P E R F S

MECHANICAL INTEGRITY TEST

0 MIN. _____ PSI

5 MIN. _____ PSI

10 MIN. _____ PSI

15 MIN. _____ PSI

PRESS CHANGE _____ PSI

CHART USED - YES _____ NO _____

MIT
PACKER
DEPTH _____CASING
SIZE 8 5/8
DEPTH 202SIZE 5 1/2
DEPTH 4759SIZE /
DEPTHSIZE /
DEPTH

PACKER 4500

ACCEPTABLE X NOT ACCEPTABLE _____

REMARKS: Flowline has been
disconnected at the water
plant. Well was shut-in
at time of inspection
J Robbins

LINER
TOP
SIZE /
DEPTHPBTVD 4734
TVD