

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

02/28/2023

Submitted Date:

03/01/2023

Document Number:

702500931**FIELD INSPECTION FORM**Loc ID 316545 Inspector Name: Burchett, Kirby On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 96850Name of Operator: TEP ROCKY MOUNTAIN LLCAddress: 1058 COUNTY ROAD 215City: PARACHUTE State: CO Zip: 81635**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**17 Number of Comments2 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
, TEP	(970) 285-9377	COGCCInspectionReports@terraep.com	
Kellerby, Shaun	(970) 712-1248	shaun.kellerby@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
284771	WELL	PR	02/01/2008	GW	103-10760	FEDERAL RGU 12-10-298D	PR

**General Comment:****COGCC Inspection Report Summary**

On Tuesday, 02/28/2023, Inspector Kirby Burchett, conducted a routine field inspection at TEP Rocky Mountain LLC on the RGU 12-10-298D Pad, Location #316545, in Rio Blanco County, Colorado.

This location is within or in close proximity to a Parks and Wildlife (CPW) District Wildlife Management Plan including Black Bear and High Priority/NSO/Density Habitat regulations.

Any Corrective Actions from previous Inspections are still applicable.

While there, I observed normal production operations. During this inspection the following compliance issues were observed:

1. Chemical and Methanol tanks lack required labeling.
- Refer to attached photographs for Corrective Action.

A follow up on this site inspection will be conducted to ensure all compliance issues have been corrected to comply with COGCC rules.

**Location**Overall Good: ☐**Signs/Marker:**

Type	OTHER		
Comment:	Separator units include attached storage tanks. The sight glass located on the side of the unit indicates the storage tank is full of an unknown fluid. No form of labeling or markers are present to identify a potential hazard or the contents of the storage tank.		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment: 911 / (970) 285-9377

Corrective Action:

Date: \_\_\_\_\_

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

Type	SEPARATOR		
Comment:	Hog panels		
Corrective Action:		Date:	
Type	TANK BATTERY		
Comment:	Hog panels		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Livestock panels		
Corrective Action:		Date:	

**Equipment:**

Type: Horizontal Heated Separator	# 1		corrective date
Comment:	Separator/dehydrator combination unit		
Corrective Action:		Date:	

Type: Ancillary equipment	# 1	
Comment:	Methanol tank inside metal containment. Operator information needs to be updated.	
Corrective Action:	All Tanks with a capacity of 10 Barrels or greater will be labeled or posted with the following information: Name of Operator; Operator's emergency contact telephone number; Tank capacity; Tank contents; and NFPA label or equivalent globally harmonized label.	Date: 03/27/2023
Type: Ancillary equipment	# 1	
Comment:	Chemical tank on plastic containment. No NFPA labeling on tank.	
Corrective Action:	Containers that are used to store, treat, or otherwise handle a hazardous material and which are required to be marked, placarded, or labeled in accordance with the U.S. Department of Transportation's Hazardous Materials Regulations, will retain the markings, placards, and labels on the Container. Such markings, placards, and labels will be retained on the Container until it is sufficiently cleaned of residue and purged of vapors to remove any potential hazards.	Date: 03/27/2023
Type: Gas Meter Run	# 1	
Comment:	Inside separator.	
Corrective Action:		Date:
Type: Bradenhead	# 1	
Comment:	Bradenhead valves are accessible.	
Corrective Action:		Date:
Type: Deadman # & Marked	# 2	
Comment:		
Corrective Action:		Date:
Type: Dehydrator	# 1	
Comment:	Separator/dehydrator combination unit	
Corrective Action:		Date:
Type: Bird Protectors	# 4	
Comment:		
Corrective Action:		Date:
Type: Plunger Lift	# 1	
Comment:	Well is on plunger lift	
Corrective Action:		Date:

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	300 BBLS	HEATED STEEL AST		,
Comment:	End of loadline has a bull plug in place.				
Corrective Action:					Date:

**Paint**

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Adequate	Walls Sufficent	Base Sufficent	Adequate	
Comment:					
Corrective Action:					Date:

Contents	#	Capacity	Type	Tank ID	SE GPS	
CONDENSATE	1	300 BBLS	HEATED STEEL AST		,	
Comment:	End of loadline has a bull plug in place.					
Corrective Action:						Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Adequate	Walls Sufficent	Base Sufficent	Adequate	
Comment:					
Corrective Action:					Date:

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:			Date:

**Flaring:**

Type			
Comment:			
Corrective Action:			Date:

Inspected Facilities									
Facility ID:	284771	Type:	WELL	API Number:	103-10760	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Plunger lift								
Corrective Action:				Date:					

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Berms						
		Berms				
				Material Handling And Spill Prevention		
Ditches						
		Culverts				
Compaction						
Gradient Terraces						
		Ditches				
		Compaction				

Comment:

Corrective Action:

Date:

**Pits:** ☒ NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
702500939	Inspection Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6037555">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6037555</a>