

STATE OF  
COLORADO

O'Malley - DNR, Anna &lt;anna.omalley@state.co.us&gt;

---

**Potential Gas Leak well API# 045-06441 (Clough Federal #14-24A-6S-94W)**

---

O'Malley - DNR, Anna <anna.omalley@state.co.us>  
To: dlemon@mustangresourcesllc.com

Wed, Mar 8, 2023 at 10:18 AM

Good Morning Ms. Lemon,

Yesterday (3/7/2023) I observed bubbles rising in the stormwater inundated well cellar for well API# 045-06441 (Clough Federal #14-24A-6S-94W) indicative of a potential gas leak. See attached photos. I immediately called the emergency contact number listed on location and spoke with the call center at 12:51 pm. The call center indicated that they would notify me upon making contact with Mustang. I have not heard back.

The area around the wellhead was observed to be inundated with stormwater. Due to the potential risk of stormwater contamination water must be removed.

Please investigate this issue immediately. A Field Inspection Report is forthcoming with the following corrective actions related to this issue:

1. Securely fasten all valves, pipes, fittings, and Production Facilities to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 608.e. 24 hours to fix the leak or isolate leak. **Corrective action date 3/8/2023**

2. Remove water from well cellars. **Corrective action date 3/9/2023**

Best,  
-Anna

--

Anna O'Malley  
Reclamation Specialist  
(she/her)



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

C: (720) 902-0775  
1120 Lincoln St. Suite 801  
Denver, CO 80203  
[anna.omalley@state.co.us](mailto:anna.omalley@state.co.us) | [www.colorado.gov/cogcc](http://www.colorado.gov/cogcc)

---

**2 attachments**

**TC\_02765.JPG**  
3756K



**TC\_02762.JPG**  
2248K