



00325711

# RADO OIL & GAS CONSERVATION COMMISSION FIELD INSPECTION REPORT



<input checked="" type="checkbox"/> NOTICE OF UNSATISFACTORY INSPECTION <input type="checkbox"/> NOTICE OF SATISFACTORY INSPECTION		1120 Lincoln Street, Suite 801 Denver, CO 80203 (303)894-2100	
API No. 05- 121 - 05466		LEASE NAME: WFL #13	
LOCATION: SWSW 19-38-55		OPERATOR: H+R	
DATE: 9-30-96		INSPECTOR: EBBinDay	
Insp. Type: SR	Insp. Status: PA	PA: Y <input type="radio"/> N <input checked="" type="radio"/>	Pass/Fail: P <input type="radio"/> F <input checked="" type="radio"/> Viol: Y <input type="radio"/> N <input checked="" type="radio"/> NOV: Y <input type="radio"/> N <input checked="" type="radio"/>

INSPECTION ITEM	COMMENTS	INPUT
<b>Well ID Signs</b> (Rule 210, 604.c(4))	H+R cementing well previously	
<b>Pits (Reserve/Production)</b> (Rule 902, 903, 904, 905)	cement pad.	
<b>Fences</b> (Rule 603.b.7, 604.C.(3), 1002.A)	Commission has no record	
<b>Tank Battery Equipment</b> (Rule 603.b.3, 604)	of plugs for this well.	
<b>Fire Walls/Berms/Dikes</b> (Rule 603.b.12, 604)		
<b>General Housekeeping</b> (Rule 603)		
<b>Spills (Oil/Water)</b> (Rule 907)		
<b>Bradenhead</b> (Rule 207.b)		
<b>Drilling Well/Workover</b> (Rule 317)		
<b>Surface Rehabilitation</b> (Rule 1002, 1003, 1004, 1103)	cultivated area	
<b>Miscellaneous</b>		

**CORRECTIVE ACTION REQUIRED:** Verify cement plugs —  
Remove cement & Restore site

Date Corrective Action Required By: 10-30-96

Date Remedied:

This report is a Notice of Inspection. The Commission requires that you correct any deficiencies shown on this report in a timely manner. Failure to comply may result in enforcement action by the Commission.