

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type	UNUSED EQUIPMENT		
Comment:	Unused/disconnected equipment. See attached photos.		
Corrective Action:	Comply with Rule 606	Date:	05/08/2023
Type	TRASH		
Comment:	Trash on location . See attached photos.		
Corrective Action:	Comply with Rule 606.	Date:	04/08/2023
Type	OTHER		
Comment:	Appears to be stained soil. See attached photos.		
Corrective Action:	Conduct maintenance on equipment, cleanup stained material and review self inspection processes per Rule 1002.(2).d.	Date:	04/08/2023

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 251121 Type: WELL API Number: 123-18924 Status: SI Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: PRODUCTION RECORDS

Comment:

Corrective Action:

Date:

Reclamation - Storm Water - Pit						
Storm Water:						
Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel		Gravel				
Comment: <input style="width:90%;" type="text"/> Corrective Action: <input style="width:90%;" type="text"/>						Date: _____
Pits: <input type="checkbox"/> NO SURFACE INDICATION OF PIT						

COGCC Comments		
Comment	User	Date
<p style="color: blue;">THIS IS A FOLLOW UP INSPECTION TO PREVIOUS INSPECTION DOC#: 696304519. All previous corrective actions assigned to this location appears to be resolved. 3 new corrective actions were observed while re-inspecting location. Please review description below for additional information on my findings.</p> <p>COGCC Inspection Report Summary **Weather Conditions: cloudy, dry ground On Wednesday, March 8, 2023 at approximately 11:30, I, Inspector Brittani Santistevan, conducted an on-site inspection at LIND 24-1 (Edge Energy), at location #: 311876 in WELD COUNTY Colorado. While there, I observed a shut in location. During this inspection the following possible compliance issues were observed: 1. Appears to be stained soil in engine house and west of pumpjack. Conduct maintenance on equipment, cleanup stained material and review self inspection processes per Rule 1002.(2).d. (Corrective Action Date: April 8, 2023) See attached photos: 7-8. 2. Trash near wellhead. Remove to comply with Rule 606. (Corrective Action Date: April 8, 2023) See attached photos: 5, 7. 3. Unused/disconnected equipment at wellhead. Remove or reconnect equipment per Rule 606. (Corrective Action Date: May 8, 2023) See attached photos: 5-6. A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.</p>	santistb	03/09/2023

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
679605467	Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6045862