

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

03/08/2023

Submitted Date:

03/10/2023

Document Number:

708200033

FIELD INSPECTION FORMLoc ID 317498 Inspector Name: Edwardson, Dylan On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 76840

Name of Operator: SCHNEIDER ENERGY SERVICES INC

Address: P O BOX 889

City: FORT MORGAN State: CO Zip: 80701

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

7 Number of Comments

4 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
SCHNEIDER, JEFF	970-867-9437	jeff@schneiderenergy.com	Principal Agent
Heibel, Krystal		krystal.heibel@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
238513	WELL	PA	06/21/2021	OW	123-05372	APRIL 12-14	RI
317498	LOCATION	AC			-	APRIL-67N60W 14SWNW	RI

General Comment:

This is a Final Reclamation Inspection for PA Well AP#123-05372 on an active location with facilities and pits. Well was plugged and abandoned 6/21/2021.

LocationOverall Good: ☐

Emergency Contact Number:

Comment: Corrective Action: Date: **Good Housekeeping:**

Type	UNUSED EQUIPMENT		
Comment:	During this inspection Staff observed sucker rod in one of the pits, pipe, and a road drag on location. Refer to attached inspection photos.		
Corrective Action:	Comply with Rule 606 and remove any unused equipment.	Date:	03/25/2023
Type	TRASH		
Comment:	Staff observed trash on the southern end of the reclaimed portion of the location. Refer to attached inspection photos.		
Corrective Action:	Comply with Rule 606 and dispose of trash.	Date:	03/18/2023

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	238513	Type:	WELL	API Number:	123-05372	Status:	PA	Insp. Status:	RI
Facility ID:	317498	Type:	LOCATION	API Number:	-	Status:	AC	Insp. Status:	RI

Environmental**Spills/Releases:**

Type of Spill: _____ Estimated Spill Volume: _____

Comment: Appears operator is in the process of closing 3 of the 4 pits on location under Remediation Project #21609. Most recent F27 Supplemental (Doc #4030024633) states proposed completion of site investigation is 05/16/2022. Staff unable to locate any documentation from the Operator for soil sample analysis related to pit closures.

Corrective Action: **Operator shall submit Supplemental Form 27 with soil samples for pit closures.** Date: 04/25/2023

Reportable: _____ GPS: Lat _____ Long _____

Proximity to Surface Water: _____ Depth to Ground Water: _____

Water Well Complaint:

DWR Receipt Num: _____ Owner Name: _____ GPS : _____ Lat _____ Long _____

Field Parameters:

Sample Location: _____ Comment: _____

Reclamation - Storm Water - Pit**Interim Reclamation:**

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: _____

Comment: _____

1002 SITE PREPARATION AND STABILIZATION

1002a. FENCING _____

Comment _____

Corrective Action _____

Date _____

1002b. SOIL REMOVAL AND SEGREGATION _____

Comment _____

Corrective Action _____

Date _____

1002c. PROTECTION OF SOILS _____

Comment _____

Corrective Action _____

Date _____

1002E. SURFACE DISTURBANCE MINIMIZATION _____

Comment _____

Corrective Action _____

Date _____

1003a. Waste and Debris removed? _____

Comment _____

Corrective Action _____

Date _____

Unused or unneeded equipment onsite? _____

Comment _____

Corrective Action _____

Date _____

Pit, cellars, rat holes and other bores closed? _____

Comment _____

Corrective Action _____

Date _____

Guy line anchors marked? _____

Comment _____

Corrective Action _____

Date _____

- 1003b. Area no longer in use? _____ Production areas stabilized ? _____
- 1003c. Compacted areas have been cross ripped? _____
- 1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____
- Cuttings management: _____
- 1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____
- Production areas have been stabilized? _____ Segregated soils have been replaced? _____

RESTORATION AND REVEGETATIONCropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced _____ Recontoured _____ 80% Revegetation _____

1003e. INTERIM VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% _____

TRANSECT RESULTS OF REFERENCE AREA% _____

TOTAL % OF DESIRABLE VEGETATION COVER _____

VEGETATIVE COVER _____

1003 f. Weeds Noxious weeds? _____

Comment _____

Corrective Action _____ Date _____

Overall Interim Reclamation

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: _____

Reminder: _____

Comment: _____

Well plugged Pass Pit mouse/rat holes, cellars backfilled _____

Debris removed Pass No disturbance /Location never built _____

Access Roads Regraded _____ Contoured Pass Culverts removed _____

Gravel removed Pass

Location and associated production facilities reclaimed _____ Locations, facilities, roads, recontoured _____

Compaction alleviation _____ Dust and erosion control _____

Non cropland: Revegetated 80% _____ Cropland: perennial forage _____

Weeds present _____ Subsidence _____

1004.d. FINAL VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% _____

TRANSECT RESULTS OF REFERENCE AREA% _____

TOTAL % OF DESIRABLE VEGETATION COVER _____

VEGETATIVE COVER _____

Comment: During this inspection, Staff observed that the well portion of the location appears to have been reclaimed with evidence of contouring and regrading, and the removal of debris/equipment. As noted in previous inspection (Doc #697503732) the Operator shall continue final reclamation activities once the pit closures are approved. Refer to attached inspection photos.

Corrective Action:						Date	
Overall Final Reclamation	In Process	Well Release on Active Location	<input type="checkbox"/>	Multi-Well Location	<input type="checkbox"/>		

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: This location does not comply with Rule 1002.f. Sediment laden stormwater has discharged off location along the southern perimeter and onto adjacent lands. Rill and gully erosion was observed throughout the location, originating northwest of the western most pit. Operator needs to install sufficient erosion and sediment control BMP in accordance with good engineering practices, immediately. Refer to attached inspection photos for documentation.

Date: 03/14/2023

Corrective Action: Immediately install or repair required BMPs per Rule 1002.f. in accordance with good engineering practices. Submit photo documentation within FIRR once work is completed.

Pits: ☐ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
708200037	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6047064